Form 3160-5. (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

| CHMDDV | NOTICES | AND | DEDODTS | ON WELLS |
|---------------|---|-----|---------|------------|
| ~ I IIVI IM Y | 101111111111111111111111111111111111111 | | REPUBLS | INV VVPIIS |

Jicarilla Apache 102 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals Jicarilla Apache 111 ALBUQUERED & Advantant Designation 1. Type of Well ⊠ Ges Weil B. Well Name and No. Other 2. Name of Operator Jicarilla Apache 102 Attention: 9. API Well No. **Amoco Production Company** Patty Haefele 3. Address and Telephone No. 3003906715 P.O. Box 800, Denver, CO 10. Field and Pool, or Exploratory Area 80201 (303) 830-4988 Basin Dakota/BS Mesa Gallup 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1600' FNL 1800' FEL Sec. T 26N R 4W Unit G Rio Arriba **New Mexico** CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans Notice of Intent Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Mill up packer Final Abandonment Notice Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Amoco Production Company requests permission to mill up the packer between the Dakota and Gallup formation per the attached procedure. 02-16-1996 Chief, Lands and Mineral Resources FEB 2 8 1996 Approved by Conditions of approval, if any

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully

representations as to any matter within its jurisdiction.

to make to any department or agency of the United States any false, ficticious, or fraudulent statements or

SJOET Well Work Procedure

Wellname:

JICARILLA APACHE 102-9

Version:

1

Date:

14-Fcb-96

Budget:

Repair Well Expense

Repair Type: Mill Up Packer

Objective: Increase gas prodution by milling up the packer that is set between the Gallup and Dakota formations, lowering 2-3/8" tubing to 8345' and returning the well to production. This welbore is already downhole commingled through an open sliding sleeve.

Pertinent Information:

Location:

G04 26N 04W,

1600 FNL 1800 FEL

FM:

DK, GP

County:

Rio Arriba

API:

3003906715

State:

New Mexico

Engr:

Steve Smethie

Lease:

Indian

Phone: H--(303)770-2180

Well FLAC: 924179

W--(303)830-5892

TD: 8416

PBTD: 8378

Economic Information:

APC WI: 100%

Prod. Before Work: 90 MCFD

Estimated Cost: \$35,000

Anticipated Prod.: 240 MCFD

Payout: 9 Mo

Max Cost-12 Mo. P.O.: \$47,000

PV 15:

\$M

Max Cost PV 15:

\$M

Note: Economics will be run on all projects that have a payout exceeding ONE year.

Formation Tops:

| Nacimento: |
|----------------|
| Ojo Alamo: |
| Kirtland Shale |
| T 1.1 1 |

Menesee:

5835

le:

Pt Lookout: Mancos Shale: 6155 6255

Fruitland: **Pictured**

3995

Gallup: Graneros: 7363 8192 8330

Lewis Shale: Cliff House:

4090 5700

Dakota:

Morrison:

Bradenhead Test Information:

Test Date: 6/4/95

Tubing: 368

Casing: 388

BH: 5

Time

BH

CSG

388

INT

CSG

5 min: 10 min:

5 0

388

15 min:

Comments:

SUGGESTED WORKOVER PROCEDURE

- 1. Unseat the seal assembly from the Baker Model D packer set at 8076' in the 4-1/2" 10.5 and 11.6 #/Ft, J-55, ST&C and LT&C casing and pull the 2-3/8" tubing.
- 2. Mill up and pluck the packer set at 8076' utilizing the air package and the booster compressor.
- 3. Clean out the wellbore to the PBTD of 8378' by running a bit and scraper. Sweep the wellbore clean.
- 4. TIH with a Mule Shoe, SN, and 2-3/8" tubing. Land the tubing intake at 8345".
- 5. Broach the tubing to be sure there are no tight spots. We may want to run a plunger in the wellbore at a later date.
- 6. Swab the well in if necessary and notify the pumper that the well has been returned to production.