

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals

5. Lease Designation and Serial No.
Tract 251 Contract 154
6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Jicarilla Apache 9
DHC #1224

9. API Well No.

30-039-08181

10. Field and Pool, or exploratory Area

Jicarilla
Basin Dakota / Mesa Verde

11. County or Parish, State

Rio Arriba NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Marathon Oil Company

3. Address and Telephone No.

P.O. Box 2409 Hobbs, NM 88240

(505) 393-7106

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL A, Sec. 28, T-26-N, R-5-W
990' FNL and 1100' FEL

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other **Downhole Commingle**
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Marathon Oil Company proposes to pull the coil tubing and release the packer, and rerun a single string of tubing to more efficiently downhole commingle the above referenced well.

(Downhole Commingle No. 1224.)

Please see the attachment for summary of work to be performed.

RECEIVED
JAN 16 1998
OIL CON. DIV.
DIST. 3

RECEIVED
BLM
97 NOV 14 PM 2:19
070 FARMINGTON, NM

14. I hereby certify that the foregoing is true and correct

Signed Kelly Cook Title Records Processor Date 11/12/97

(This space for Federal or State office use)

Approved by [Signature] Title Chief, Lands and Mineral Resources

Conditions of approval, if any:

Date JAN 13 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

DHC-1224 (2)

Jicarilla Well No. 9
Pull Coil Tubing & Packer. Rerun single string of tubing.

Procedure

1. **MIRU Coil Tubing Unit. POOH with 1.5" coil tubing. RDMO CTU.**
2. **MIRU PU. ND wellhead and NU BOP equipment.**
3. **Release packer and POOH, laying down packer. If packer came out, go to Step # 8.**
4. **If packer will not release, RU wireline company. Freepoint tubing. Set plug in profile below packer. Cut tubing just above Freepoint. RD wireline company.**
5. **POOH with tubing. PU washpipe and TIH to just above fish. RU air foam unit.**
6. **Wash over fish to top of packer. Circulate hole clean. POOH with washpipe.**
7. **TIH with overshot and latch onto fish. Release packer and POOH, laying down fish.**
8. **TIH with bit to top of fill. RU air foam unit. Clean out fill to PBTD. POOH.**
9. **TIH with RBP and packer. Set RBP below Dakota perforation and packer above Dakota perforation. Acidize Dakota perforations.**
10. **Release packer. Go down hole and latch and release RBP. PU to below the Mesa Verde perforations. Set RBP below Mesa Verde perforation and packer above Mesa Verde perforation. Acidize Mesa Verde perforations.**
11. **Release packer. Go down hole and latch and release RBP. POOH, laying down RBP and packer.**
12. **TIH with collar and SN on 2 3/8" production tubing. Land tubing at the top Dakota perforation.**
13. **ND BOP equipment and NU wellhead. RDMO PU.**
14. **Open well and test.**