

## **Amoco Production Company**

Petroleum Center Building 501 Airport Drive Farmington, New Mexico 87401

L. O. Speer, Jr. Area Superintendent

June 26, 1975

File: LOS-252-400.1

Mr. Emery C. Arnold New Mexico Oil Conservation Commission 1000 Rio Brazos Road Aztec, New Mexico 87410

Dear Sir:

Re: Containment of Bradenhead Leak Jicarilla Contract 155 No. 20 N-29-26-5

As per our discussion this morning, we are forwarding to you a wellbore diagram for our Jicarilla Contract 155 No. 20 well, which is a dual completion in the Gonzales Mesaverde and the Dakota. This well developed a leak across the long string as indicated on the wellbore diagram at 330-20' KB. We ran a "Borehole Audio Tracer Survey" (BATS) log to find this leak and to confirm that: 1) the bradenhead valve was not leaking and 2) gas was not channeling beneath the surface casing shoe.

As per your recommendation we are instituting a regular check on the bradenhead pressure to assure that gas is contained within the long string-surface casing annulus. We will monitor this pressure once a week for one month and thereafter once every three months and will forward this information to your office.

If you require any further information please feel free to contact us.

Yours very truly,

BWR/en Attachment



## Amoco Production Company

FILE	· · · · · · · · · · · · · · · · · · ·
4.0.04	

		EN	GINEERII	NG CHART			APPN			
subjectJicar	illa Contract	155 No	. 20				DATE		· · · · · ·	
Dual:	Dual: Gonzales Mesaverde-Dakota				BY					
							1	:		:
				:	6488¹ :	КВ		:	:	
							1	1	•	1
			1 ) 1	1 1 -	6434	GL				
						:		:		:
							:	i	:	
				.				!		
							:	•		•
					_		•		•	:
,				Ψ	Suspect	ted hol	e 330-	320	•	
							•		. ,	•
					8-5/8" Circ.	24# CS. 5 sx.	446°	<b>x</b> 3	300	sx.
0.0/011										, ! -
2-3/8" tubing SA 68	342'.								:	
						- i		:	•	
			中丨	#	DV SA	2926'.			•	
						•		· ·		
						*	• • • •	•	÷	
Mesaverde Perforati	ons •							•	•	
4877-82', 4960-70 5003-08', 5034-39	', 4992-97'					÷ .		: •	:	
5065-70', 5100-05	', 5051-56' ', 5124-28'							• •	•	
									٠	
									•	
			4	1 7	DV SA 5	287'.				
Dakota Perforations 7066-72', 7078-80 7156-58', 7162-70			X		Packer	@ 6842 <b>'</b>	•			
7240-501										
	•		ı							

4-1/2" 10.5# CSA 7327'. 1st Stage x 600 sx, No circ. 2nd Stage x 600 sx, Circ. 175 sx.

3rd Stage x 750 sx, Circ. 100 sx.

Ferm 371 2.7

## SURFACE CASING LEAK TEST

Date of	Test	perator Amoco	Production Company
Lease Na	me <u>Jicarilla Contract 15</u> 5	Well No. <u>20</u>	U <u>N</u> Sec. <u>29</u> T <u>26</u> R <u>5</u>
Initial	Pressure Before Shut-In:	Surface Casing	285
		Long String	285
	SH	UT-IN PRESSURE	
	Surface Casing		Long String
5 Min.	288		288
10 Min.	288		288
15 Min.	288		288
20 Min.	290		290
25 Min.	290		290
30 Min.	290		290
,	The Gonzales Mesaverde by stop cock.	zone was shut-in 3	hours and 20 minutes  (IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
ВҮ:	Fil Spein Ja	<del></del>	
	Area Superintendent		