Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT -" for such proposals Jicarilla Apache	SUNDRY NOTICES AN	D REPORTS ON WELLS	Jicarilla Contract 117
SUBMIT IN TRIPLICATE 1. Type of Well			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE 1. Type of Well		· · · · · · · · · · · · · · · · · · ·	lionnilla Annaha
SUBMIT IN TRIPLICATE Type of Well	Use APPLICATION FOR	PERIVIT - for such proposals	
1. Type of Well	SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
S. Well Name and No. Since		30	
2. Name of Operator ENERGEN RESOURCES CORPORATION 3. Address and Telephone No. 2198 Bloomfield Highway, Farmington, NM 87401 4. Location of Well (Prootage, Sec., T., R., M., or Survey Description) 1700' FSL, 1800' FWL, Sec. 33, T26N, R3W, N.M.P.M. 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Notice of Intent Recompletion Non-Routine Fresturing Water Shut-Off Conversion to Injection Dispose Water (None: Report results of multiple completion or Notice) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and tones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wirreline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 12/1/99 Swab back load.			8 Well Name and No.
3. Address and Telephone No. 2198 Bloomfield Highway, Farmington. NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1700' FSL, 1800' FWL, Sec. 33, T26N, R3W, N.M.P.M. 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Respect Plugging Back Plugging Back Non-Routine Fracturing Water Shut-Off Conversion to Injection Other Dispose Water (Roce: Report results of multiple completion on Wed Completion or Recompletion Recompletio	well Other	FED	
3. Address and Telephone No. 2198 Bloomfield Highway, Farmington. NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1700' FSL, 1800' FWL, Sec. 33, T26N, R3W, N.M.P.M. 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Respect Plugging Back Plugging Back Non-Routine Fracturing Water Shut-Off Conversion to Injection Other Dispose Water (Roce: Report results of multiple completion on Wed Completion or Recompletion Recompletio		BEO 5000 S	
2198 Bloomfield Highway, Farmington, NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1700' FSL, 1800' FWL, Sec. 33, T26N, R3W, N.M.P.M. 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Notice of Intent Abandonment Notice Plugging Back Conversion to Injection Dispose Water (Note: Report results of multiple completion or Well Conversion to Injection and Indige completion Report and Log form) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1700' FSL, 1800' FWL, Sec. 33, T26N, R3W, N.M.P.M. 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Notice of Intent Recompletion Plugging Back Casing Repair Casing Repair Altering Casing Other Reperf Other Notice Report results of multiple completion recompletion or Well Completion or Recompletion recompletion or Report results of multiple completion report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.	•	Terri " Wilder " William "	30-039-21197
1700' FSL, 1800' FWL, Sec. 33, T26N, R3W, N.M.P.M. 11. County or Parish, State Rio Arriba NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Plugging Back Plugging Back Plugging Back Plugging Back Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion or Wet Completion or Recompletion or Report subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab.			
11. County or Parish, State Rio Arriba NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Report Other Report saults of multiple completion on Well Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab.			Blanco mesaverde
Rio Arriba NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Report Other Other Report Other Other Report Other Other Report Other Report Other Other Report Other Other Report Other Other Report Other Other Other Report Other Othe	1700 13E, 1000 1ME, 300. 33, 120M	(7) NOW, W.M.1 .M.	11 County of Barish State
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Non-Routine Fracturing Plugging Back Casing Repair Altering Casing Other Report Other Report Other Report Other Report Other Other Report Other Report Other Report Other Other		Cocco Co. Home	· · · · · · · · · · · · · · · · · · ·
TYPE OF SUBMISSION Notice of Intent Notice of Intent Notice of Intent New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Altering Casing Other Reperf Dispose Water (Note: Report results of multiple completion or Well Completion or Recompletion or	OUEOK ADDDODDIATE DOV(.)) TO INDICATE MATURE OF MOTION CORNE	
Notice of Intent Abandonment	12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, C	OR OTHER DATA
Recompletion New Construction Non-Routine Fracturing Water Shut-Off Casing Repair Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion or Recompletion or Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. Swab back load.	TYPE OF SUBMISSION	TYPE OF ACTION	
Subsequent Report Recompletion	Notice of Intent	Abandonment	Change of Plans
Subsequent Report		Recompletion	
Final Abandonment Notice Casing Repair Altering Casing Other Reperf Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.	X Subsequent Report	· ·	
Final Abandonment Notice Altering Casing Other Reperf Dispose Water (Note: Report results of multiple completion on Wet Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.			
Dispose Water (Note: Report results of multiple completion on Wel Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.	Final Abandonment Notice		
(Note: Report results of multiple completion on Wel Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.			Conversion to Injection
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dril give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.		Other Repert	
11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.			Completion or Recompletion Report and Log form.)
11/29/99 MIRU. TOH. RU wireline. Perf Point Lookout from 6120-6190 with 1SP/3ft for a total of 23 holes. 11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.	 Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true verti 	pertinent details, and give pertinent dates, including estimated date of starting	any proposed work. If well is directionally dril
11/30/99 TIH with packer set at 6035'. Acidize with 2000 gals 15% HCL. RU swab. 12/1/99 Swab back load.			
12/1/99 Swab back load.	11/29/99 MIRU. TOH. RU wireline. Per	rf Point Lookout from 6120-6190 with 1SP/3ft	for a total of 23 holes.
	11/30/99 TIH with packer set at 603	5'. Acidize with 2000 gals 15% HCL. RU swab.	
	12/2/99 Swab		
12/3/99 Release packer. TOH. Ran 198 jts 2 3/8 4.7# J-55 tubing set at 6177'. Kick well off.	12/3/99 Release packer. TOH. Ran 19	98 jts 2 3/8 4.7# J-55 tubing set at 6177'. K	ick well off.

Signed Monuce Coff	Title Production Assistant	
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title Fertion Eg	Date 62-03.00

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.