Form 9-331 (May 1983)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved.
Rudget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

DELVI	1 171 1-13	1 01	 1 1-	117	
	C=01	0010	~ 1.1		-1/

GEOLOGICAL SURVEY	03331			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
Ge ATTENTION 200 2	7. UNIT AGREEMENT NAME			
WELL GAS OTHER				
NAME OF OPERATOR	S. FARM OR LEASE NAME			
Caulkins Oil Company ADDRESS OF OPERATOR	9. WELL NO.			
P.O. Box 340. Bloomfieli, New Mexico	1.93			
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT			
860 from the South and 950 from the West	Gouth-Blanco-Otaro-Chac 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA			
	Section 7 25 61			
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Rio Arriba Hew Hexico			
Check Appropriate Box To Indicate Nature of Notice, Report, or				
NOTICE OF INTENTION TO:	QUENT REPORT OF:			
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL			
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING			
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT*			
REPAIR WELL CHANGE PLANS (Other) (Other) (Note: Report result Completion or Recompletion of R	ts of multiple completion on Well spletion Report and Log form.)			
nent to this work.) *				
Spud 1:00 PA 7-5-77 Drilled 12 1/4" hole to 141' and cementel 7 5/6 at 141' with 150 sacks E, Jaul. Flug Jown 3:00 Cement circulated to surface. Fested surface casing with 500, 7-6-77. To decafter testing 30 minutes.				
Drilled 12 1/4" hole to 141' and cementel 6 5/3 at 141' with 150 sacks E, Jaul. Flug lown 3:00 Cement circulated to surface. Tested surface casing with 500# 7-6-77. To dec				
Drilled 12 1/4" hole to 141' and cementel * 5/8 at 141' with 150 sacks E, Jaul. Plug Jown 3:00 Cement circulated to surface. Pested surface casing with 600; 7-6-77. To decafter testing 30 minutes.				
Drilled 12 1/4" hole to 141' and cementel * 5/8 at 141' with 150 sacks E, Jaul. Plug Jown 3:00 Cement circulated to surface. Pested surface casing with 600; 7-6-77. To decafter testing 30 minutes.				
Drilled 12 1/4" hole to 141' and cemented 5/8 at 141' with 150 sacks 8,5 3a31. Flug Dwn 3:00 Jenent circulated to surface. Pested surface casing with 500,6 7-6-77. To decay after testing 30 minutes.	crease in pressure			