

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER | 5. LEASE DESIGNATION AND SERIAL NO. NM 014733 |
| 2. NAME OF OPERATOR Merrion Oil & Gas Corporation | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| 3. ADDRESS OF OPERATOR P. O. BOX 840, Farmington, New Mexico 87499 | 7. UNIT AGREEMENT NAME |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL and 990' FWL | 8. FARM OR LEASE NAME North Lindreth Com |
| 14. PERMIT NO. | 9. WELL NO. 1A |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7313' GL | 10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde |
| | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T26N, R2W |
| | 12. COUNTY OR PARISH Rio Arriba |
| | 13. STATE New Mexico |

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☒

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANE ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We request permission to repair this well. Surface pressures declined suddenly in May and the well has been unable to produce. We suspect there is a hole in the casing. We propose to pull tubing and set a bridge plug above the Mesaverde perfs. A packer will be run and we will pressure test. If a leak is found deep in the well, we will squeeze with cement (Exact cement volumes will depend on depth, existing cement, etc.) If a leak is found shallow, we will back off casing and replace the bad joint.

RECEIVED

JUN 19 1986

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

JUN 20 1986

OIL CON. DIV.
DIST. 3

19. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 6/19/86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMCC