Form 9-331 (May 1963)	UNITED STATE DEPARTMENT OF THE		IT IN TRIPLICATE instructions on re-	5. LEASE DESIGNATION	u No. 42-R1424.
GEOLOGICAL SURVEY				Mims No. 1 SF 078067	
SUN (Do not use this	IDRY NOTICES AND REP	ORTS ON WEL	LS erent reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
1.				7. UNIT AGREEMENT NA	ME
WELL GAS WELL	Carson Unit				
2. NAME OF OPERATOR	8. FARM OR LEASE NAME				
Shell Oil Comp	Unit 9. WELL NO.				
1700 Broadway	24-14				
4. LOCATION OF WELL (1	10. FIELD AND POOL, OR WILDCAT				
See also space 17 bel At surface	Bisti				
600' FSL &	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA Section 14-T25N-R12W				
14, PERMIT NO.	15. ELEVATIONS (Show	whether DF, RT, GR, etc.)		12. COUNTY OR PARISH	13. STATE
,	6422.2	?' KB		San Juan	N.M.
16.	Check Appropriate Box To I	ndicate Nature of N	otice, Report, or Ot		1 21111
	NOTICE OF INTENTION TO:	1	SUBSEQUE	ENT REPORT OF:	
TEST WATER SHUT-C	PULL OR ALTER CASING	WATE	R SHUT-OFF	REPAIRING V	WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRAC	TURE TREATMENT	ALTERING C.	
SHOOT OR ACIDIZE	ABANDON*	SH00	TING OR ACIDIZING	ABANDONME	NT* X
REPAIR WELL (Other)	CHANGE PLANS	(Oth	(Note: Report results of Completion or Recomplet	of multiple completion	on Well
proposed work. If nent to this work.)		urface locations and me	sured and true vertical	depths for all marker	s and zones perti-
	AL SUNDRY WHEN LOCATION EADY FOR INSPECTION		SEP 33	1977 COM-	
SIGNED(This space for Federal	eral or State office use)		Opers. Engr.	DATE	2 7 1977
APPROVED BY CONDITIONS OF A	PPROVAL, IF ANY:	ITLE		_ DATE	

cc: NMO&GCC

PLUG & ABANDON		
SHELL OIL COMPANY	LEASE CARSON UNIT	BISTI
FROM: 9/22/77	DIVISION WESTERN ELEV COUNTY SAN JUAN STATE	24-14 6422.2 KB NEW MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 24-14
(P&A)

"FR" TD 5010. PB 4943. AFE #570806 provides funds to plug & abandon well. 9/17 RU Bedford & pulled tbg. Ran 50 jts workstring. 9/19 Fin'd run'g workstring to PBTD. Spt'd 25 sx cmt plug over & above Gallup perfs. Pulled workstring & set jacks. 9/20 Shot csg @ 1164 & spt'd 50 sx cmt plug over csg stub - Pictured Cliffs & Fruitland Coal. Pulled csg to 340 & spt'd 35 sx cmt plug over 0jo Alamo Sd. Pulled csg to 180 & spt'd 25 sx cmt plug over sfc csg stub. Pulled rest of csg out of hole. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford. FINAL REPORT