## **DIL CONSERVATION COMMISSION**

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

July 23, 1964

Shell Oil Company Box 1200 Farmington, New Mexico

Attn: Bob Kasarian
Division Production Superintendent

Dear Sir:

We received two copies of Mederal Sundry Report on Wells pertaining to your Carson Unit #11-13 located in Section 13-25N-12W.

Information contained on this form indicates that the casing has failed. You have stated that no remedial action is contemplated due to the fact that the production rate will not justify repair work.

New Mexico Dil Conservation Commission rules require that you either repair the casing in this well or permanently plug and abandon it. In the light of the above information will you please indicate what action you intend to take and when such action will be taken.

Yours very truly

BCA: ks

Emery C. Arnold Supervisor, District #3

cc: United States Geological Survey
Box 959
Farmington, New Mexico

## DIL CONSERVATION COMMISSION

IDEO RIO BRAZOS ROAD AZTEO, NEW MEXICO

A CONTRACTOR OF STREET

ang katalayan ilga da Malay bara Sanakan sang bara

ing the state of t

53 5 5 5 5 5 5

 $\frac{1}{2} \left( \frac{1}{2} \left$ 

The control of the co

and the second of the second o

and a special contract of

Sec. 18.3

i je programa i programa. Programa i programa i

्रक्षा । अन्य क्षित्र क्षेत्र हेन्द्र क्षेत्र

and the second of the second