

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.
L. M. Phillips No. 1
SF 078063

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Shell Oil Company

3. ADDRESS OF OPERATOR
1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**660' FSL & 1980' FEL of Sec. 7, T25N,
R11W, NMPM, San Juan Co., N.M.**

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6385.5' KB

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

9. WELL NO.

34-7

10. FIELD AND POOL, OR WILDCAT

Basti

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

**Sec. 7, T25N,
R11W, NMPM**

12. COUNTY OR PARISH 13. STATE

San Juan

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attached abandonment prognosis



18. I hereby certify that the foregoing is true and correct

SIGNED

R. Plautky

TITLE

Division Operations Engr.

DATE

JUN 22 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

CC: NMOCC

Alap

*See Instructions on Reverse Side

24" $\frac{8\frac{5}{8}}{107}$ "

Plug and Abandonment
Carson Unit 34-7
Section 7, T 25 N, R 11 W
San Juan County, New Mexico

Pertinent Data

TD: 5080' PBTD: 5063'
8 $\frac{5}{8}$ " Csg. @ 107'

4 $\frac{1}{2}$ " Csg. @ 5073' w/ 150 sax.

7 $\frac{7}{8}$ " Hole

Elevation: 6385.5' KB


KB - GL = 10'

Permanent Datum = KB

Past and current status: Presently T.A'd.
Has only 7' of ML pay in the GD sand.
Initial prod: Pumped 180 BDO.

Proposed Work: Plug and Abandon

1. Pull equipment. If tubing is openended, lower to PBTD, load hole with mud. (Add 20 sax aquagel + 1 sack Benes per 100 bbls of mud or 20 sax salt gel per 100 bbls mud).
2. Spot 20 sax Class "G" cement mixed w/1# flocele/sack over perforations and above perforations. Minimum requirements - 100' cement plug above perforations. W.O.C. 12 hrs.
3. Pull tubing.
4. Rig up casing pullers. Determine casing free point.
5. Attempt to shoot and pull casing at free point (theoretical cement top at 4320'). Top of Mancos Shale 3872'. Do not spend more than 3 hrs. on attempt to pull casing. If unable to pull any casing go to step 8.
6. If casing is recoverable, place cement plugs by cementing through casing or running tubing inside of csg. as it is pulled. Spot Class "G" cement plugs as follows:
 - a. 150' plug across stub of 4 $\frac{1}{2}$ " casing. (50' in casing, 100' in open hole)
 - b. 200' plug from top of Fruitland Coal at 1210' to 1410'.
 - c. 150' plug across base of Ojo Alamo sand at 370'. (100' below base of sand and 50' above base of sand).
 - d. 100' plug across shoe of 8-5/8" casing (30' in casing, 70' in open hole).
 - e. 10 sack plug at surface.



7. Install permanent abandonment marker as follows:

Steel marker at least 4 inches in diameter set in concrete and extending at least 4' above mean ground level. The name and number of the well and its location (Unit letter, section, township and range) shall be welded, stamped, or otherwise permanently engraved into the metal marker.

(Continuation from Step 5)

8. Perforate 4 1/2" casing w/4 JSPP as follows:

- a. Fruitland Coal - Pictures Cliffs interval 1230' to 1231'.
- b. Below Ojo Alamo sand from 470' to 471'.

- 9. Run tubing, spot a 50 sack Class "G" cement plug from 1230' to 590'.
- 10. Pull tubing to $\pm 400'$, close bradenhead, displace 20 sax through perforations 1230' to 1231'. WOC 2 hours.
- 11. Pull tubing to perforations 470' to 471'.
- 12. Load 4 1/2" casing with cement (\pm 30 sax) and pull tubing. With bradenhead open, displace 20 sax cement through perforations 470' to 471'.
- 13. Spot 10 sack plug at surface.
- 14. Install abandonment marker as outlined in step 7.

JAC
COC:maf

J. A. Stanzione