

October 23, 1981

Hixon Development Company
501 Airport Drive
Farmington NM 87401

Re: CBU GI-14 G-8-25N-12W
CBU WI 11 K-6-25N-12W

Gentlemen:

Annual packer tests on the above-referenced injection or SWD wells indicate a packer or tubing leak.

In order to insure the protection of hydrocarbon bearing and fresh water zones, you are hereby directed to initiate remedial action within sixty days.

Yours truly,

Jeff A. Edmister
Deputy Inspector

JAE:gc

cc: ~~Operator file~~ *well file*
Prentice Childs