

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Huerfano Unit
2. NAME OF OPERATOR El Paso Natural Gas Company	8. NAME OF LEASE NAME Huerfano Unit
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	9. WELL NO. 154
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790 'N, 1650 'W	10. FIELD AND POOL, OR WILDCAT Undes. Pic. Cliffs
11. SEC. T. R. M. OR ALK. AND SURVEY OR AREA Sec. 1, T-25-N, R-10-W N. M. P. M.	12. COUNTY OR PARISH San Juan
13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST AFTER SHUT-OFF  
FRACTURE TREATMENT  
SHOOT OR ACIDIZING  
REPAIR WELL  
(Other)

PULL OR ALTER CASING  
MULTIPLE COMPLETS  
ABANDON\*  
CHANGE PLANS

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recuplication Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plug and abandon this well in the following manner:

MOL&RU. Release Halliburton R-3 packer. Round trip tubing set 2000'. Circulate hole with 9# mud. Spot 120 sx. cement to cover open hole and casing approximately 1760-2233'. Fill 1380-1760' with 9# mud. TOOH with tubing. Run wireline. Shoot two holes @ 1330'. Deadhead 35 sx. plug 1280-1380' and squeeze. Wireline shoot two holes @ 150' and squeeze circulate 65 sx. cement to surface with bradenhead open. Cut off wellhead and set plug and abandonment marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Clerk

DATE

10-13-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

10-13-87

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

NMOCC