Budget	Bureau No.	42-R358.4
Form A	pproved.	

(l	eb. 19	951)	
			_

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Senta Pa
Lease No.	S7-080490
Unit	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION			1 0				
NOTICE OF INTENTION				ENT REPORT OF W			
NOTICE OF INTENTION			1 11	NT REPORT OF S			
NOTICE OF INTENTION NOTICE OF INTENTION				INT REPORT OF A			
NOTICE OF INTENTION				NT REPORT OF R			
NOTICE OF INTENTION			1 1	NY REPORT OF A NYARY WELL HIS			
NOTICE OF INTENTION			SOFFEEME	WELL HIS			
	(INDICATE AR	BOVE BY CHECK MA	IRK NATURE OF REP	ORT, NOTICE, OR C		<u></u>	
Federal "mm"	•		*************	2 CAT (18)	iy as	·	19.63
Well No. 1-3	is located	790 ft. fro	$\sum_{n=1}^{N}$ line a	nd 790 f	$f_{\text{from}} \left\{ \frac{E}{E} \right\}$	ine of sec.	3
Mik of Sec.		25-H	ARREA .		XXXXXX	inc or sec.	
(½ Sec. and Sec.		(Twp.)	(Range)	(Meridia			
Wildest Gall	•		Juan	(Mendia	···/	Mand	
(Field)			ty or Subdivision)		(State or Te	rritory)	
The elevation of t	ha damiah Aa		11 :. 439 4	. (1		DE C	E C C
ne elevation of	the derrick floo	or above sea	level is	rt.			
		DET	AILS OF WO	RK		** N. C.	7 1963
State names of and exp	ected depths to obje	ctive sands; show	sizes, weights, and	lengths of propos	ed casings; indica	ite mudding jobs	
		ing points, and a	ll other important	proposed work)			
						HER PERIO	MIDAL DI SIO
						U. S. CECLO	
Pc11mA	hala wish					FARMINGTON	I, NEW MEXI
	hole with m		esed perfer	etione 590	19-6006 vi	FARMINGTON	I, NEW MEXI
regular nest	coment, C	at 45" eas:	ing at 2779	' and pull	led. Set	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 26	cement. C 29 to 2729.	set 85 a	ing at 2779 ack plug at	' and pull	led. Set	FARMINGTON	I, NEW MEXI
regular nest	cement. C 29 to 2729.	at 45" eas:	ing at 2779 ack plug at	' and pull	led. Set	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 28 surface plug	cament, C 29 to 2729, . Marker p	ut 4½" eas: Set 85 e/ ipe was ex	ing at 2779 ack plug at acted.	and pull 2310 to 2	led. Set 1966. Set	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 28 surface plug	cament. C 29 to 2729. . Marker p	nt 44" eas: Set 85 eas: ipe was exc	ing at 2779 ack plug at acted.	and pull 2310 to 2	led. Set 1966. Set	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h	cament. C 29 to 2729. . Marker p	nt 44" eas: Set 85 eas: ipe was exc	ing at 2779 ack plug at acted.	and pull 2310 to 2	led. Set 1966. Set	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h	cament. C 29 to 2729. . Marker p	nt 44" eas: Set 85 eas: ipe was exc	ing at 2779 ack plug at acted.	and pull 2310 to 2	led. Set 1966. Set	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h	cament. C 29 to 2729. . Marker p	nt 44" eas: Set 85 eas: ipe was exc	ing at 2779 ack plug at acted.	and pull 2310 to 2	REGIETATION	FARMINGTON th 10 seci 22 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h is ready for	cament, C 29 to 2729. . Marker p ave not bee inspection	nt 45" eas: Set 85 ei ipe was ex: n removed:	ing at 2779 nek plug at acted. from legati	' and pull 2310 to 2	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h is ready for I understand that th	cament. C 29 to 2729. Marker p eve not bee inspection	Set 85 et 1pe was exc. R removed :	ing at 2779 nek plug at acted. from legati	' and pull 2310 to 2	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h is ready for I understand that th	cament. C 29 to 2729. . Marker p eve not bee inspection is plan of work mus	set 85 er Set 85 er I pe was er R removed :	ing at 2779 nek plug at acted. from legati	' and pull 2310 to 2	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI
regular neat plug from 28 surface plug Tanks h is ready for I understand that th	cament. C 29 to 2729. Marker p eve not bee inspection	set 85 er Set 85 er I pe was er R removed :	ing at 2779 nek plug at acted. from legati	' and pull 2310 to 2	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI
Tenks h is ready for I understand that th Company	coment. C 29 to 2729. . Marker p ave not bee inspection is plan of work mus John H. Tri	nt 4½" eas: Set 85 ec 1pe was exc R removed: treceive approval gg Gempany Box 106	ing at 2779 nek plug at acted. from legati	and pull 2310 to 3	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI
Tenks h is ready for I understand that th Company	cament. C 29 to 2729. . Marker p eve not bee inspection is plan of work mus	nt 4½" eas: Set 85 ec 1pe was exc R removed: treceive approval gg Gempany Box 106	ing at 2779 nek plug at acted. from legati	' and pull 2310 to 2	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI
Tenks h is ready for I understand that th Company	coment. C 29 to 2729. . Marker p ave not bee inspection is plan of work mus John H. Tri	nt 4½" eas: Set 85 ec 1pe was exc R removed: treceive approval gg Gempany Box 106	ing at 2779 sek plug at seted. from locati in writing by the C	and pull 2310 to 3	REGIONAL MARS	th 10 seck 10 seck 10 seck 10 seck	I, NEW MEXI