Feb. 1	951)	ı	

(SUBMIT IN TRIPLICATE)

UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

Land Office	New	Mexico	
Lease No.	04224		
Unit	qui	treu	

NOTICE OF INTENTION TO DRILL				
	SUBSE	EQUENT REPO	RT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSE	QUENT REPO	RT OF SHOOTING OR ACIDIZING.	
NOTICE OF INTENTION TO TEST WATER SHUT			RT OF ALTERING CASING	EIVEH
NOTICE OF INTENTION TO RE-DRILL OR REPA			RT OF RE-DRILLING OR REPAIR	_ X
NOTICE OF INTENTION TO SHOOT OR ACIDIZ			RT OF ABANDONMENT	2 1959
NOTICE OF INTENTION TO PULL OR ALTER CA NOTICE OF INTENTION TO ABANDON WELL		EMENIARY W	ELL HISTORY	OGICAL SURV
			U S 4501	N NEW MEX
(INDICATE ABOV	E BY CHECK MARK NATURE OF	REPORT, NOT	ICE, OR OTHER DATA	••••
		D	ecember 29	, 19
Vell No. 12 is located 15	ft. from $\begin{cases} N \\ S \end{cases}$ lin	e and	1500ft. from W line o	f sec. 10
W Sec. 10	25M (M		H.K.P.M.	
7.	(Twp.) (Range)	• ••	(Meridian)	_
ullard F. C. (Field)	Sen Juan (County or Subdivision		(State or Territory)	· ·
his well was plugged and . Spotted 25 sack coment	plug from cleans	ed out d	epth (2350') to 21	50'. Fietu
Cliffs perforations ve				
Cliffs perforations we have off 5 1/2" easing			asing stub.	
Cliffs perforations we have off 5 1/2" casing by Spotted 25 sack cement Flaced 10 sack cement	plug in top of !	5 1/2° c	4" x 4' marker on	d restored
Cliffs perforations we have off 5 1/2° casing Spotted 25 sack cement	plug in top of !	5 1/2° c	4" x 4' marker on	d restored
Cliffs perforations we have off 5 1/2" casing by Spotted 25 sack coment Placed 10 sack coment	plug in top of !	5 1/2° c	4" x 4' marker on	d restored 1958.
Cliffs perforations we have off 5 1/2" casing botted 25 sack cement Placed 10 sack cement	plug in top of !	5 1/2° c	4" x 4' marker on	d restored 1958.
Cliffs perforations we have off 5 1/2" casing by Spotted 25 sack coment Placed 10 sack coment	plug in top of !	5 1/2° c	4" x 4' marker on	d restored 1958. MAD
Cliffs perforations we have off 5 1/2" casing botted 25 sack cement Placed 10 sack cement	plug in top of ; plug at surface, contours. Pluggir	5 1/2" o erected ng compl	eted December 18,	1958. [[VED] N5 1959
Cliffs perforations we shot off 5 1/2° casing spotted 25 sack cement. Placed 10 sack cement location to original of sack description to original of sack cement.	plug in top of plug at surface, contours. Pluggir	5 1/2" o erected ng compl	eted December 18,	1958. [[VED] N5 1959
Cliffs perforations we shot off 5 1/2° casing 5 5potted 25 sack cement 1. Placed 10 sack cement	plug in top of plug at surface, contours. Pluggir	5 1/2" o erected ng compl	eted December 18,	1958. [[VED] N5 1959
Cliffs perforations we shot off 5 1/2° casing 5 spotted 25 sack cement 6. Placed 10 sack cement 1 location to original continuous to original company 21 haso Matural ompany 207	plug in top of plug at surface, contours. Pluggir	5 1/2" c erected ag compl	sted December 18.	1958.
Cliffs perforations well. Shot off 5 1/2° casing 3. Spotted 25 sack cement Placed 10 sack cement location to original continuous to original company I understand that this plan of work must resombly the sack cement location to original company Box 997	plug in top of plug at surface, contours. Pluggir	5 1/2" c erected ag compl	eted December 18,	1958.

COVIDATE

14,40) to

DOIX SALE WAS DETENDED TO