

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

5. LEASE DESIGNATION AND SERIAL NO.

NM-16463

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WEL  GAS WEL  OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Kirby Exploration Company

8. FARM OR LEASE NAME

Federal

3. ADDRESS OF OPERATOR

P.O. Box 1745, Houston, Texas 77001

9. WELL NO.

1-33

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1160' FSL & 790' FWL

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec 33 - 25N - 8W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6787

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*


Well was plugged and abandoned as follows:

1. Went in hole with drill pipe and spotted 75 sack cement plug from 2000 feet to total depth 2352.
2. Spotted 50 sack cement plug from 400 to 600 feet.
3. Set 25 sack cement plug in surface pipe.
4. Cut off bradenhead and welded on dry hole marker.
5. Fenced pits. Same will be covered when dry.


APPROVED

JUN 29 1978

P. T. McGRATH



BLM RECEIVED  
FARMINGTON  
APR 26 1977



18. I hereby certify that the foregoing is true and correct

SIGNED

*William T. Jones*  
William T. Jones

TITLE

Agent

DATE

4-21-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*vmcc*