

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

January 10, 1986

Mr. Ewell N. Walsh Walsh Engineering & Production Corp. P.O. Drawer 419 Farmington, NM 87401

Re: M.J. Brannon Federal 20 #1R J-20-25N-9W

Dear Red:

As per our previous conversation there is a strong possibility that there is a casing leak in the referenced well as indicated by the dramatic decrease in water production after the installation of a packer. Because of this indication, you are directed to install an inert packer fluid in the annular area and pressure test it to see if a leak exists.

Sincerely,

Frank T. Chavez

District Supervisor

FTC/dj

xc: Well File

Operator File