
	9-881 a
(Feb	. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Form Ap	proved.
and Office	New Mexico
Oll-A	
	E / 2

SUNDRY NOTICES AND REPORTS ON WELLS

		C. Beeson Neal, Agent inFarmington
:	Farmington, New Mexico	By
Address	TOY 150	1/25/14/100
Company	Box 728	
Company	J. Glenn Turner	
I understand tha	at this plan of work must receive approval in	writing by the Geological Survey before operations may be commenced.
		1
Dec. 29, 1961 - Shut well in to await potential test and pipe line connection.		
pin collar	on bottom joint. Landed t	ubing at 2645'.
Dec. 28	, 1961. Ran 82 joints 1-1	/2" Jal Con Weld tubing with Aztec joints,
after 21,00	· — —	T) natte arear to,000 gar, and t) more
gallons water	er - 24,000# sand - 10-20	. Breakdown 1700 to 1500. Max. 3000. 15 balls after 10,000 gal, and 15 more
shots/ft: 2665'-2672'; 2682'-2726'; 2705'-2712'. Sand fractured: 42,000		
Dec. 27, 196	61. Tested casing with 25	00 psi. Held OK. Perforated with 4 jet
(State names of and	expected depths to objective sands; show six ing points, and all c	es, weights, and lengths of proposed casings; indicate mudding jobs, cement- other important proposed work)
	5 -111.	ILS OF WORK Page 2.
The elevation of	of the derrick floor above sea le	vei is <u>~722~</u> ft.
(So. Blanco	P. C. Ext.)	1: 6.560 6
(Field	RIO AITIDA C	or Subdivision) (State or Territory) 2 1002
Basin Dakot		(Range) (Meridian) (LULIVII)
NE/4 Section		7 17 1 1 1 1 1 1 1 1 1
Well No. 1-26		
	Turner - Quantius	[N] line and 790 to from [E] line of sec. 26
		<u> </u>
		January 27, 1962 19
	(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)
NOTICE OF INTENT	TION TO ABANDON WELL.	
	FION TO PULL OR ALITER CASING	SUPPLEMENTARY WELL HISTORY
1	TION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENT	TION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
	TION TO CHANGE PEARS	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENT	TION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF SENIG TRECTUTING SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING