UNITED STATES


DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ces and Reports on Wells : !		
	000 EEE LOVOL 10	5.	Lease Number SF 079367
. Type of Well GAS	and the second s	6.	If Indian, All. or Tribe Name
	- DEADENE		TT-16 2 None
2. Name of Operator	(D) (2) (E) II U U U	13/	Unit Agreement Name SAN JUAN 27-5 UNIT
BURLINGTON	M DEC 2 7 1989	₩••	
TO PROVIDE TO A TOTAL TOTAL TO A TOTAL	& GAS COMPANY	×77	
	ONE GOLD EN	^{1,1} 28.	Well Name & Number
Address & Phone No. of Operat		0	SAN JUAN 27-5 UNIT API Well No.
PO Box 4289, Farmington, NM	8/499 (505) 326-9/00		300390677400
Location of Well, Footage, Se	ec., T, R, M	10.	Field and Pool
890' FSL, 1800' FEL Sec. 31, T-27-N, R-05-W, NMPM		11	South Blanco PC
		11.	County and State Rio Arriba Co, NM
	DICATE NATURE OF NOTICE, REPORT, Type of Action	OTHER	DATA
Type of Submission X Notice of Intent		of Pla	ans
	Recompletion New Co		
Subsequent Report	Plugging Back Non-Ro		Fracturing
Final Abandonment	Casing Repair Water Altering Casing Conver	Shut o	
Final Abandonment	X Other - Restimulation		o 1111/0002011
46	leted Operations		
13. Describe Proposed or Compl	•		
1. MOL and pressure test	casing.		
 MOL and pressure test Acidize and foam fract 	casing.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. 	casing. ture treat PC zone.		
 MOL and pressure test Acidize and foam fract Clean out well. Return well to product 	casing. ture treat PC zone. tion.		
 MOL and pressure test Acidize and foam fract Clean out well. Return well to product 	casing. ture treat PC zone.	·	
1. MOL and pressure test 2. Acidize and foam fract 3. Clean out well. 4. Return well to product	casing. ture treat PC zone. tion.		ce <u>12/08/99</u>
1. MOL and pressure test 2. Acidize and foam fract 3. Clean out well. 4. Return well to product 14. A hereby certify that the Signed Signed Old	casing. ture treat PC zone. tion. foregoing is true and correct. Title Regulatory Administra	tor_Dat	

SAN JUAN 27-5 UNIT #93

Section 31 O, T-27 -N R-05 -W Rio Arriba, New Mexico

South Blanco Pictured Cliffs Field Wellbore Schematic



File: Q:\area\!pcteam\2000\welldata\Rigless Slimhole\Wellbore Diagram.doc