

EL PASO NATURAL GAS COMPANY
DUAL COMPLETION
Initial Packer Leakage Test

October 21, 1958

San Juan 27-5 Unit No. 32 (M)(P) G 1550N, 1550E; 25-27-5 Rio Arriba

Mesa Verde and Pictured Cliffs 3657

Mesa Verde


October 7, 1958

Pictured Cliffs 995 33

Pictured Cliffs 995

Mesa Verde 1139 33

TIME MINUTES	(MV) FLOWING PRESSURES PSIG	(MV) WORKING PRESSURES PSIG	(PC) SIP (C) PSIG	TEMP °F
0			995	
15	445		997	61
30	398		997	61
45	363		998	61
60	348		998	61
180	286	Calc. 295	1000	62



Mesa Verde 3636 4641

James B. Goodwin

Pictured Cliffs

October 21, 1958

Pictured Cliffs 1010 47

Pictured Cliffs 1011

Mesa Verde 1136 14

TIME MINUTES	(PC) FLOWING PRESSURES PSIG	(PC) WORKING PRESSURES PSIG	(MV) SIP (T) PSIG	TEMP °F
15	616	625	1136	58
30	594	576	1136	59
45	497	516	1137	60
60	466	479	1137	61
180	289	305	1139	62

Pictured Cliffs 3673 4002

D. K. Bryant

REMARKS:

The results of this test indicate

☒ No Packer Leakage in this well
☐ Packer Leakage

The well (May or ~~may~~) be produced as desired

EL PASO 150 (0-58)

J. L. Goodwin
Signed