5 BLM 1 File

Form 3160-5 (June 1990)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31,1993

SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Designation and Serial No. SF 078155
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			6. If Indian, Allotted or Tribe Name
Use "APPLICATION FOR PERMIT -" for such proposals			
SUBMIT II	N TRIPLICATE		
1. Type of Well Gas		nesse. Otto e nnesse	7. If Unit or CA, Agreement Designation
Well Well	X Other	Injector Well	West Bisti Unit
2. Name of Operator		RAFINAR	8. Well Name and No.
Dugan Production Corp.		EU EI WEIN	West Bisti Unit #153
3. Address and Telephone No.	(505) 325 - 1821	AUG 1 0 1999 U	9. API Well No.
P.O. Box 420 , Farmington, NM 87499 Location of Well (Footage, Sec., T., R., M., or Survey Description)	(505) 525 - 1621	1.00 1 0 1898 -	30 045 05619 10. Field and Pool, or Exploratory Area
Location of vveil (Poolage, Sec., 1., K., M., of Sulvey Description)	<u> </u>	L COM. DIV.	10. Field and Pool, of Exploratory Area
1990' FSL & 1960' FWL		DIST. 3	*Bisti Lower Gallup
Sec. 35, T26N, R13W, NMPM		ション (c)	11. County or Parish, State
			San Juan, NM
12. CHECK APPROPRIATE BOX(s) TO INC	DICATE NATURE OF		OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	0 (8)
X Notice of Intent	Abandonment Recompletion		Change of Plans
Subsequent Penert	Plugging Back		New Construction Non-Routine Fracturing
Subsequent Report	Casing Repair		Water Shut-Off
Final Abandonment Notice	Altering Casing		Conversion to Injection
		Repair casing or plug	Dispose Water
		Kopan dading of plag	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Operator intends to repair casing or plug this well. The well is temporarily abandoned with a cement plug from 2814'-3617' with a cast iron bridge plug set above the Gallup perforations and capped with 35' of cement. Plan to repair the casing leak, drill out existing plugs, and return the well to injection service. If the casing can not be repaired, the well will be plugged. The exact plugging procedure will depend on the intervals squeezed during the repair attempt. BLM and Navajo EPA will be consulted to obtain a plugging plan. The formation tops to be covered, if plugging is pursued are: Ojo Alarno - above surface casing at 214' Fruitland - 885' Pictured Cliffs - 1230' Mesaverde - 2010' Gallup - 4816'			
14. I hereby portify that the forencies is true and assent			
14. I hereby certify that the foregoing is true and correct Signed John Alexander	Title Vice-presiden	t Date	57 8/4/99
(This space for Federal or State office use)			
Approved by /S/ Duane W. Spencer	Team Load, Pea	তিহিন্দ্রকার Date	Alb - 6 North
Conditions of approval, if any:			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

