## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checki	ng Below	
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
NOTICE OF INTENTION TO PLUG WELL	Notice of Intention to Plug Back	Notice of Intention to Set Liner  Notice of Intention to Shoot (Nitro)	
Notice of Intention o Squeeze	Notice of Intention to Acumze		
NOTICE OF INTENTION O GUN PERFORATE	Notice of Intention (Other)	Notice of Intention (Other) Sandfree	x
OIL CONSERVATION COMMISSI ANTA FE, NEW MEXICO	<del></del> :	April 29, 19	58
entlemen:		,= 1.7	
Following is a Notice of Intention	to do certain work as described below at the.	The Buitish_American (41)	Pandunda
(Company or O	Salge "B" Lease	Well Noin	(Unit)
	34, T2611, R1311	MPM.,Bisti-Gallup	Рс
foot. Swab test, ru	ean out to 5110' PBD. Perfers in Baker full bore packer on to oil into tubing to check for	bing & set @ 4990 KB. F communication between	411
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa	n Baker full bore packer on to oil into tubing to check for Pull tubing & packer & swal adfres w/30.000# sand in 30.00	abing & set @ 4990! KB. F emmunication between test. Set cast iron bri O gallens crude using 40	dge nylon
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa core balls after fir	n Baker full bore packer on to oil into tubing to check for Pull tubing & packer & swal	abing & set @ 4990! KB. F communication between test. Set cast iron bri O gallens crude using 40 drill out bridge plug and	dge nylon
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa core balls after fir out to 5110' KBD. R	n Baker full bore packer on to oil into tubing to check for . Pull tubing & packer & swai undfras w/30,000# sand in 30,00 st 15,000 gallons. Swab csg,	emmunication between test. Set cast iron brico gallens crude using 40 drill out bridge plug and on production.	dge nylon clean
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000! KB. Sa core balls after fir out to 5110! KBD. R	m Baker full bore packer on to cil into tubing to check for . Pull tubing & packer & swal mdfras w/30,000# sand in 30,00 st 15,000 gallons. Swab csg, un the & rods and place well of	emmunication between test. Set cast iron brico gallens crude using 40 drill out bridge plug and on production.	dge nylon clean
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa core balls after fir out to 5110' KBD. R	m Baker full bore packer on to oil into tubing to check for . Pull tubing & packer & swall adfrace w/30,000# sand in 30,00 est 15,000 gallons. Swab esg, am the & rods and place well of	abing & set @ 4990! KB. F communication between test. Set cast iron bri O gallens crude using 40 drill out bridge plug and	dge nylon clean
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa core balls after fir out to 5110' KBD. R	m Baker full bore packer on to cil into tubing to check for . Pull tubing & packer & swall adfrace w/30,000# sand in 30,00 est 15,000 gallons. Swab csg, and the & rods and place well of the state of the British By	sping & set & 4990' KB. Fearminication between to test. Set cast iron bridge plug and drill out bridge plug and on production.    April	dge nylon clean
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa ecre balls after fir out to 5110' KBD. H  Approved	m Baker full bore packer on to cil into tubing to check for . Pull tubing & packer & swai mdfras w/30,000 sand in 30,00 st 15,000 gallons. Swab csg, nun tbg & rods and place well of By	communication between test. Set cast iron bridge plug and on production.    Continue of the co	dge nylen clean
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa core balls after fir out to 5110' KBD. H  Approved	m Baker full bore packer on to cil into tubing to check for . Pull tubing & packer & swaindfras w/30,000f sand in 30,00 st 15,000 gallons. Swab csg, cun the & rods and place well of By	sping & set & 4990' KB. From the seminication between the test. Set cast iron bridge plug and drill out bridge plug and on production.  1958  19	dge nylen clean
foot. Swab test, ru annulus w/eil. Pump perferated intervals plug @ 5000' KB. Sa core balls after fir out to 5110' KBD. H  Approved	m Baker full bore packer on to oil into tubing to check for a Pull tubing & packer & swain adfrace w/30,000# sand in 30,00 est 15,000 gallons. Swab esg, and the & rods and place well of the By	sping & set & 4990' KB. From the seminication between the test. Set cast iron bridge plug and drill out bridge plug and on production.  1958  19	dge nylen clean

•	OIL CONSERVATION	I COMMISSION
	No. Copies Receive	OFFICE
	DESTRICT	100.
	perator panta Fig.	
	U S. G. 3	
	Transporter	

 $\mathfrak{S}^{(n)}$