Form 3160-5 (June 1990)

### UNITED STATES

PORM APPROVED			
Budget Bun	esu No.	1004-0135	
Expires:	March	31, 1993	

DEPARTMENT OF THE INTERIOR	Expires: March 31, 1993
BUREAU OF LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS	( : 21 SF 078091
Do not use this form for proposals to drill or to deepen or reentry to a different res	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT—" for such proposals	Production of the second of th
	Aiyu
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well	West Bisti Unit
X Well Gas Other	8. Well Name and No.
2. Name of Operator	West Bisti Unit 132
Dugan Production Corp.	9. API Well No.
3. Address and Telephone No.	30-045-05670
P.O. Box 420, Farmington, NM 87499 (505) 325-1821	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Bisti Lower Gallup
1980' FSL - 660' FEL	11. County or Parish, State
Sec. 28, T26N, R13W, NMPM	San Juan, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, F	EPORT OR OTHER DATA
TYPE OF SUBMISSION TYPE OF AC	
	, non
Notice of DECEMEN Abandonment	Change of Plans
Recompletion	New Construction
AUG () 9 1001	Non-Routine Fracturing
First Abademus Nation	Water Shut-Off
Final Abandosment Notice Alterlag Casing Cother Cother	Conversion to Injection
DICT O	(Note: Report results of multiple completion on Well
DIST. 3	Campleton or Basamalatica Basama e a ca
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)	starting any proposed work. If well is directionally drilled,
Plug to abandon using Class "B" cement plugs as	s follows:
1. Tag cement plug already present at 4681'.	If plug is found
on depth, Gallup (4913') is covered.	II play to found

- 2. Load hole with 9 lb./gal. mud.
- 3. Perforate 50' below Mesa Verde top (2300') @ 2350', and spot 100' cement plug inside and outside casing with 100% excess.
- 4. Perforate 50' below Chacra top ( 1631') @ 1681', and spot 100' cement plug inside and outside casing with 100% excess.
- 5. Perforate 50' below Pictured Cliffs top (1325') @ 1375', and spot cement plug to 50' above Fruitland top (1250') with 100%
- 6. Perforate 50' below surface casing (214') @ 264', and pump cement down 51 casing until cement returns to surface a braden head. Leave inside and outside of casing full of

itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United State representations as to any matter within its jurisdiction.	any false, ficultious or franculent statements
Approved by Title Title	Date
Signed	Dute /// 1/ C/
4. I hereby certify they the foregring as true and correct	00000000
7. Cut off well head and install dry hole marker.	SEE ATTACHED FUR CONDITIONS OF APPROVA

### UNITED STATES DEPARTMENT OF THE INTERIOR

## BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 132 West Brate Uni

#### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

- 2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.

# GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6#/gal slurry weight is to be used when using class B neat cement or when CaCl<sub>2</sub> is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
  - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

  Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was applugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

ද පැල්ද දෙද සහ අතු දෙකුම් දෙකුම් දිරිම විසිති අතු ද දෙද දැන විසිතිමේ විධිකර් මණකාර මේ කිරීම

The state of the s

g in a side on grift the constitution things and constitution