

Form 1000
(May 1962)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SF 080402

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CM & W Elliott

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

West Bisti

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 30
T26-N, R13-W

12. COUNTY OR PARISH 13. STATE

SAN JUAN

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CM & W Dr.
Elliott Oil Company

3. ADDRESS OF OPERATOR

Box 1355, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

SE/4 NW/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Propose to run production test to determine if well is non-commercial.
Propose to abandon if found to be non-commercial.

Procedure:

1. Cement plug 4,900' to T.D.
2. Cement plug 4,100' to 4,000'
3. Cut and pull 5 1/2" casing, placing 100' cement plug across stub.
4. Cement plug 1,500' to 1,650' across Top Picture Cliff.
5. Cement plug 400' to 550' below Ojo Alamo.
6. Cement plug at base and top of surface casing with marker installed.



18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE Owner

DATE 3/27/74

(Leave space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

