


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 0315
Unit SE/4



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Turner - Ballard - Federal
Well No. 3-15 is located 990 ft. from S line and 1800 ft. from E line of sec. 15
SE/4 Sec. 15 T 26 N R 9 W N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox San Juan Count. New Mexico.
(Field) (County or Subdivision) (State or Territory)

The elevation ~~of the derrick floor~~ above sea level is 6323 ft. - ungraded ground.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Propose to drill with rotary tools to the top of the Pictured Cliff formation - expected between 1,900 feet and 2,000 feet below surface - then drill 4-3/4" rat hole through Pictured Cliff formation. Completion with cable tools - and shooting with solidified nitroglycerin or sand oil fracturing.

Casing program: 100 feet of 8-5/8" new 8"rd. thd. 32# casing. Circulate cement to surface.

5-1/2" O.D. 17# seamless casing to be set on top of Pictured Cliffs formation, cemented with 150 sacks regular cement.

1" tubing to be set within 50 feet of total depth for production.
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company A. Glenn Turner

Address Retired, Farmington, New Mexico.

Home Office 1211 Riverside Park Building

Albuquerque, New Mexico

By [Signature]

Title C. Hanson Neal

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

10-10-68

[illegible]

J. CLAREN TURNER


Company.....~~WINDY HILL COMPANY~~.....

Lease.....~~Ballard Federal~~..... Well No.....~~3-15~~.....

Sec.....15....., T.....26 N....., R.....9 W., N.M.P.M.....

Location.....990' from the South line and 1800' from
the East line.

Elevation.....6323 Ungraded ground.....



Scale—4 inches equal 1 mile.

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Seal:

Registered Professional Charles J. Finklea
Engineer and Land Surveyor. N. Mex. Reg. No. 1302

Surveyed 10 May 19 54