

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Location well 100  
Flow Line + Tank Bldg. necessary  
dk

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
14-20-603-1412

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator CLINTON OIL COMPANY-PRODUCTION DEPARTMENT	8. Farm or Lease Name USKAYAHWOOD
3. Address of Operator 217 North Water, Wichita, Kansas 67202	9. Well No. 1
4. Location of Well UNIT LETTER _____, 660 FEET FROM THE NORTH LINE AND 1980' FEET FROM THE WEST LINE, SECTION 18 TOWNSHIP 26N RANGE 11W NMPM.	10. Field and Pool, or Wildcat GALLEGOS GALLUP
15. Elevation (Show whether DF, RT, GR, etc.) 6061 G.L.	12. County SAN JUAN

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>



17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 5240' - PBD 5197' - 8 5/8" O.D. Csg. @ 321' - 5 1/2" O. D. Csg. @ 5240'  
Perfs 5004' - 56' and 5120' - 74'

Spot 30 sxs plug across perfs, top @ 4925'. Shot 5 1/2" O. D. Csg. @ 2185'  
and pulled same. Spot plugs as follows:

30 sxs 2240-2140  
40 sxs 1350-1250  
40 sxs 400- 300

Set P & A marker with 10 sxs surface plug.  
Clean up location, well P & A, Final Report.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. W. Lang TITLE Div. Manager, Northern Div. DATE January 26, 1971

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: