UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Su	ndry Notices	and Reports on Wel	ls		
					5.	Lease Number SF-078388
1. Ту	pe of Well GAS				6.	If Indian, All. or Tribe Name
			(C)		7.	Unit Agreement Nam
	ame of Operator					
3	RESOURCES		COMPANY			Therefore to The
		OIL & GAS	COMPANI		8.	Huerfanito Unit Well Name & Number
. Ac	dress & Phone No.	of Operator				Huerfanito U #67
I	PO Box 4289, Farmir	gton, NM 874	99 (505) 326-9700		9.	API Well No. 30-045-05905
	ocation of Well, Fo				10.	Field and Pool
99	90'FSL, 1550'FEL, S	Sec ^C 12, T-26-N	, R-9-W, NMPM			Ballard Pict.Clif
					11.	County and State San Juan Co, NM
.3.		_X_d or Completed	Altering Casing _ Other - Restimula Operations the Pictured Cliff wing procedure:	te		
		n open hole lo	ean out open hole togs. Run 3 1/2" cas		_	th at approximatel
	to surfac Gilsonite	, 0.4% fluid	cks Class "B" 50/50 loss, 3% Kcl. Perfo	poz w/2% prate, acid	gel, lize a	0.3% CFR-3, 5 pps
	to surfac Gilsonite	, 0.4% fluid	cks Class "B" 50/50 loss, 3% Kcl. Perfo	poz w/2% prate, acid	gel, lize a	0.3% CFR-3, 5 pps nd foam fracture
	to surfac Gilsonite	, 0.4% fluid	cks Class "B" 50/50 loss, 3% Kcl. Perfo	poz w/2% prate, acid	gel, lize a	0.3% CFR-3, 5 pps nd foam fracture
	to surfac Gilsonite	, 0.4% fluid	cks Class "B" 50/50 loss, 3% Kcl. Perfo	poz w/2% prate, acid	gel, lize a	0.3% CFR-3, 5 pps nd foam fracture
14.	to surfac Gilsonite treat the	, 0.4% fluid : Pictured Cli	cks Class "B" 50/50 loss, 3% Kcl. Perfo	o poz w/2% prate, ació an out and	gel, lize a	0.3% CFR-3, 5 pps nd foam fracture
14. Signe	I hereby certify	, 0.4% fluid Pictured Cli	cks Class "B" 50/50 loss, 3% Kcl. Perfo ffs formation. Clea	o poz w/2% prate, ació an out and correct.	gel, lize a retur	0.3% CFR-3, 5 pps nd foam fracture n well to producti
Signe	I hereby certify	that the fore	cks Class "B" 50/50 loss, 3% Kcl. Performation. Clear going is true and the matter of the company of the compan	o poz w/2% prate, ació an out and correct.	gel, lize a retur	0.3% CFR-3, 5 pps nd foam fracture n well to producti

Mend TX order &

,

Huerfanito Unit # 67 Pertinent Data Sheet

API#: 300450590500

Location: 990 'FSL & 1550 'FEL, Unit O, Section 12, T26N, R09W, San Juan County, New Mexico

Latitude: 36 ° - 29.87' Longitude: 107 ° - 44.21'

Field: Ballard PC Elevation: 6231 'GL TD: 2019'

6242 'KB PBTD: 2019'

<u>DP#:</u> 49076A

 Spud Date:
 12/14/54
 Compl Date:
 12/28/54
 Lease:
 NM 4520-300 (Fed)

 GWI:
 84,738 %

Initial Potential: Initial Potential = 1443 Mcfd NRI: 71.817%

Orig SIP = 666 psi Prop#: 0-079708-00

Casing Record:

Depth Set (Ft.) Cement (Sx.) Cement (Top) Wt. (#'s) & Grade Hole Size (In.) Csg Size (In.) circ to surf 100 24 J-55 105 8 5/8 12 1/4 1397' @ 75% eff. 100 1,955 14 J-55 5 1/2 7 7/8 1,955 -2,019 openhole 4 3/4

Tubing Record:

Tbg. Size Wt. & Grade Depth Set # Joints Comments
1" 1,985' 95

Formation Tops:

Ojo Alamo: 1,140' Kirtland Shale: 1,245' Fruitland: 1,655' Pictured Cliffs: 1,942'

Logging Record:

Original Stimulation: SOH w/ 150 qts SNG, SOF w/ 7,100 gal diesel and 11,400# sand

Workover History: None

Production History: 7/97 PC capacity: 5.0 MCF/D. 7/97 PC cum: 734.0 MMCF.

Pipeline: EPNG

Huerfanito Unit #67

Section 12 O, T-26-N R-09-W San Juan, New Mexico

Ballard Pictured Cliffs Wellbore Schematic

