

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078944

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER
2. NAME OF OPERATOR
Bedford, Inc.
3. ADDRESS OF OPERATOR
P.O. Box E - Farmington, New Mexico
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
**1980' fsl 659' fee Sec 9, T26N, R12W
San Juan County, New Mexico**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sullivan

9. WELL NO.

1 E

10. FIELD AND POOL OR WILDCAT

Gallegos Gallup

11. SECTION, RANGE, MERIDIAN AND
SURVEY OR AREA

Sec 9, T26N R12W

NMPN

12. COUNTY OR TOWNSHIP 13. STATE

San Juan NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6061 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☒

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log forms.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (County, State, pertinent details, and give pertinent dates including estimated date of starting
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths to and from surface pertinent
to this work.)*

It is intended to plug and abandon this well in the following manner:

1. Squeeze Gallup Perfs 4977 to 5116 w/50 sx
2. Cut and pull 5 1/2" casing from approx. 1300'
3. Place 150 ft. plug inside and out of stub
4. If casing is recovered below Picture Cliff
Place 150 ft plug over Pictured Cliff
5. Place 150 ft plug from 750 to 600 @ base of Ojo Alamo
6. Erect P&A marker w/10 sx surface plug
7. Clean location

This well is not capable of producing oil or gas economically.

18. I hereby certify that the foregoing is true and correct.

SIGNED

(This space for Federal or State office use)

TITLE **President**

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 1 1972

F. T. MCGRAITH

*See Instructions on Reverse Side