

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back and direct test, only.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	NOV 13 1985
2. NAME OF OPERATOR Beta Development Company	BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA
3. ADDRESS OF OPERATOR 238 Petroleum Plaza, Farmington, NM 87401	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FSL & 790' FEL	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6124' G.L.
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 6, T-26N, R-11W
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☒

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well history:

10-3/4" set @ 219' cement circulated

4 1/2" 10.5# J-55 set @ 6245' cemented w/200 sx 50-50 pozmix + 4% gel, tailed in w/100 sx reg. no 2 stage set.

Well died 1968, repaired w/model "D" packer and kempacked, it produced in this manner until 3-73 when it died again, found holes in Chocra at 2930' to Mesa Verde section @ 4184' well was squeezed with 600 sx 14% gel. Well produced until April of 1978.

Propose to test Dakota formation in this manner:

Rig up workover rig pull 1 1/2" tubing and model "D" stinger, replace all bad tubing, go in hole and clean out to T.D. 6200', sting into model "D" packer and swab well off, test Dakota (30-60 days) if no damage, pull tubing and resqueeze well, if non-productive P & A and redrill well.

RECEIVED

NOV 15 1985

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

John B. Kuehling

TITLE

Asst. Supt.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

NOV 14 1985

DATE

November 11, 1985

AREA MANAGER

FARMINGTON RESOURCE AREA

NMOCC