

Santa Fe

(SUBMIT IN TRIPLICATE)

Land Office _____


NW 05750

Lease No. _____

Graham

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Packer leakage test indicated communication

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 14, 19 **61**


Well No. **1** is located **1850** ft. from **{N}** line and **1165** ft. from **{E}** line of sec. **9**
N 1/4 **Sec. 9** **27-N** **8-W** **N 1/2 M**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
N 1/2 South Blanco P.O. **San Juan** **New Mexico**
(County or Subdivision) (State or Territory)
Blanco (Mesa Verde)

The elevation of the derrick floor above sea level is **5931.3** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run temperature survey. Indicated leak at 3915'. Run and set Otis Type "1" packoff assembly to straddle leak. Top packoff at 3899'; bottom at 3934' with 1" J-55 tubing between packoff. Preliminary test indicates leak has been repaired. No packer leakage test being run.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **WESTERN NATURAL GAS COMPANY**
Address **623 Midland Tower**
Midland, Texas
By **Paul Woodward**
Office Manager
Title _____