

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <b>Huerfano Unit</b>
2. Name of Operator <b>El Paso Natural Gas Company</b>	8. Farm or Lease Name
3. Address of Operator <b>Box 990, Farmington, New Mexico</b>	9. Well No. <b>5</b>
4. Location of Well UNIT LETTER <b>D</b> <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>330</b> FEET FROM THE <b>West</b> LINE, SECTION <b>10</b> TOWNSHIP <b>26-N</b> RANGE <b>10-W</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>West Kutz Pictured Cliff</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>6706' GL</b>	12. County <b>San Juan</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>


### SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Due to non-production, it is intended to Plug and Abandon this well in the following manner:

1. Spot 25 sack plug in open hole.
2. Cut casing at free point.
3. Spot 25 sack plug across cut off.
4. Set 25' cement plug at surface and install 4" x 4' dry hole marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **ORIGINAL SIGNED E.S. OBERLY**

TITLE **Petroleum Engineer**

DATE **January 20, 1966**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: