

Form 3160-5  
(June 1990)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTRECEIVED  
BLM

AUG 17 PM 3:40

FORM APPROVED  
Budget Bureau No. 1004-0133  
Expires: March 31, 19935. Lease Designation and Serial No.  
SF-078899 (USA)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SW-580

8. Well Name and No.  
Oneda No. 19. API Well No.  
30-045-2066410. Field and Pool, or Exploratory Area  
Basin Dakota

11. County or Parish, State

San Juan, NM

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reenter a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

## SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Pro New Mexico, Inc.

3. Address and Telephone No.

141 E. Palace Ave., Santa Fe, NM 87501 (505)988-4171

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1850' FWL, 790' FNL, Sec. 8, T26N, R11W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

## TYPE OF ACTION

☐ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☒ Other Complete lower  
Dakota zone☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water(Note: Report results of multiple completions of well  
Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We request approval to replace the tubing in this well and stimulate and add perforations as follows:

Remove 1 1/4" tubing from hole; pick up 2 3/8 work string and run in hole with bit & casing scraper; drill out PBD to 6250'; run in hole with non-retrievable bridge plug to bottom & set; move up hole to bottom of existing perfs (6158'-6178') and spot acid (7 1/2% HCL); run cement bond, temperature, casing inspection and Gamma Ray logs; perf lower Dakota zone from 6226' to 6240', 3-4 shots per foot; run in hole with 2 3/8 tubing and set packer approximately 6212; frac lower perfs with 250 gals 7 1/2% HCL and 32,000 gallons 30# J-4; run 1 1/4 to 6230'; set wellhead and return to production.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Agent

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

AUGUST 17, 1994

SEP 08 1994

WARRANTY MANAGER