# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wel	ls
1. Type of Well GAS	5. Lease Number NMSF-078372 6. If Indian, All. or Tribe Name
2. Name of Operator MERIDIAN OIL  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	Huerfano Unit  8. Well Name & Number Huerfano Unit 243  9. API Well No. 30-045-21220 2/24  10. Field and Pool Basin Dakota  11. County and State San Juan Co, NM
4. Location of Well, Footage, Sec., T, R, M 1500'FNL, 850'FWL Sec.31, T-26-N, R-10-W, NMPM	
Subsequent Report Recompletion Plugging Back Casing Repair	, REPORT, OTHER DATA tion  Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injectio
13. Describe Proposed or Completed Operations  It is intended to plug and abandon this well per the attached procedure and well	bore diagram.
DEGETVED  MAY 2 3 1994  OUL GOV. DUV. DUST. 3	OSAL DESCRIPTION OF THE PROPERTY OF THE PROPER
I hereby certify that the foregoing is true and consigned with Still file (ROS) Title Regulatory Af (This space for Federal or State Office use) APPROVED BY Title	

DISTRICT MANAGER

## Huerfano Unit #243 (Dk)

## NW, Sec. 31, T26N, R10W San Juan County, New Mexico PLUG AND ABANDONMENT PROCEDURE

Note: All cement volumes use 100% excess outside pipe and 50' inside; mud wil. be 8.4 ppg with a 40 sec vis.)

- 1. Install and/or test rig anchors. Prepare blow pit. Comply to ail NMOCD, BLM and Meridian safety rules and regulations.
- 2. MOL and RUSU. Blow well down; kill with water if necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. POH and tally 2-3/8" tubing (6392'). **Note**: Attempted to pull tubing in September, 1990; found to be stuck at an unknown depth. Work, cut and/or fish tubing as necessary. After tubing is recovered from well then replace with a work string if necessary. PU and RIH with 4-1/2" casing scraper to 6183' or above tubing left in hole: POH and LD.
- 4. Plug #1 (Dakota perfs): PU 4-1/2" cement retainer and RIH; set at 6183'; pressure test tubing to 1000#; establish rate into DK perfs. Mix 36 sxs Class B cement and squeeze 31 sxs below retainer from 6388' to 6183', then spot 5 sxs cement above retainer. POH above cement; mix and spot mud to 5387'. POH to 5387'.
- 5. Plug #2 (Gallup top): Load well with water and circulate clean. Pressure test casing to 500#. Mix 17 sxs Class B cement and set a balanced plug from 5387' to 5217'. POH above cement; mix and spot mud to 3267'. POH to 3267'.
- 6. **Plug #3 (Mesaverde top):** Mix 12 sxs Class B cement and spot balanced plug from 3267' to 3167'. POH above cement; mix and spot mud to 1780'. POH to 1780'.
- 7. Plug #4 (PC & Ft tops): Mix 32 sxs Class B cement and spot balanced plug from 1780' to 1416'. POH above cement; mix and spot mud to 966'. POH with setting tool.
- 8. Plug #5 (Kt & OA tops): Pressure test casing to 500#. Perforate 4 holes at 966'. Establish rate into holes if casing tested. PU 4-1/2" cement retainer and RIH; set at 916'; establish rate into holes. Mix 101 sxs Class B cement and squeeze 81 sxs outside casing and spot 20 sxs cement inside casing. POH above cement; mix and spot mud to 274'. POH and LD tubing and setting tool.
- 9. Plug #6 (Surface): Perforate 2 holes at 274'. Establish circulation out bradenhead valve. Mix approximately 80 sxs Class B cement and pump down 4-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
- 10. ND BOP and cut off well head below surface casing flange and install P&A marker to BLM specs. RD and MOL. Cut off anchors.
- 11. Restore location per BLM stipulations.

Recommended:	KOStany	stary)
		0
Approved:		

#### **Pertinent Data Sheet**

May 10, 1994

Wellname: Huerfano Unit #243 DP Number: 44879A

Well Type: Basin Dakota Elevation: 6478 GL

Location: 1500 FNL, 850 FWL, Sec 31, T26N, R10W

San Juan Co., New Mexico

Ownership: GWI: 61.9% Drilling: Spud Date: 4-10-73

NRI: 46.8% **Total Depth:** 6479'

**PBTD:** 6464'

Casing and Tubing:

 Hole Size
 Size, Wt, & Grade
 Depth
 Cement
 TOC

 12-1/4"
 8 5/8", 24#, K-55
 224'
 182 cf
 Surface

 7-7/8"
 4 ½", 10.5#,J-55
 6479'
 1379 cf
 1110' T.S.

3 stage

**Tubing:** 2 3/8" EUE J-55 set @ 6392' (205 joints), SN 1 jt off bottom @ 6360'.

**Formation Tops:** 

Ojo Alamo 806' Mesaverde 3217' Kirtland 916' Point Lookout 4177' Fruitland 1466' Gallup 5267' Pictured Cliffs 1730' Graneros 6183' Dakota 6280'

Logging: IES; FDC-GR, Temp. Survey

**Stimulation:** Perf'd Dakota 6224' to 6388' w/17 shots.

Frac with 51,970 gal gel and 62,500# sand.

**Workover History:** 

Sept, 1990 - Well servicing rig attempted to pull tubing, found to be

stuck; depth unknown.

Production History: As of 3/31/94 11,746 Bbls and 1,262,888 Mcf

# EXISTING WELL

MERIDIAN OIL INC 10 MAY 94

HUERFANO UNIT #243

NW, Sec. 31, 26N, 10W

San Juan County, NM

SIRCULATED SURFACE

CEMENT

8-5/8" 24# @ 224' (182 cf cement)

OA 8 806'

Kt @ 916'

Ft @ 1466'

PC @ 1730'

MV @ 3217'

G1 @ 5267'

Gn @ 6183' Dk @ 6280'

PBTD 6464'

7-7/8" HOLE TD 6479'

TOC % 1110' T.S.;

DV Tool 3 1933' (371 of cement)

TOC 3 2336' (Cal, 75%)

DW Tool 3 4511' 661 of cement:

TCC 3 53371

# **WORKOVER HISTORY**

SEPTEMBER 1990

ATTEMPTED TO PULL TUBING, FOUND TO BE STUCK, DEPTH UNKNOWN.

2-3/8" EUE TUBING @ 6392'

Dk Perfs 6224'-6388'

4-1/2" 10.5# @ 6479' (347 cf cement)

## PLUGGED WELL MERIDIAN OIL INC 10 MAY 94 HUERFANO UNIT #243 NW, Sec. 31, 26N, 10W CEMENT CIRCULATED San Juan County, NM SURFACE 8-5/8" 24# @ 224' (182 of dement) PLUG #6 274'- SURFACE 80 SXS CEMENT PERFORATE @ 274' OA @ 806' CEMENT RT @ 916' PLUG #5 966'-756' Kt @ 916' PERFORATE @ 966' 20 SXS INSIDE 81 SXS OUTSIDE TOC 3 11101 (T.S.) FT @ 1466' PLUG #4 1780'-1416' PC @ 1730' 32 SXS CEMENT DV Tool @ 19331 (371 of cement) TOO @ 23361 [Cal, 75%) PLUG #3 3267'-3167' MV @ 3217' 12 SXS CEMENT DV Tool 3 4511\* :661 of cement: Gl @ 5267' PLUG #2 5387'-5217' TOD @ 53371 17 SXS CEMENT Cal, 75%) **CEMENT RT @ 6183'** Gn @ 6183' Dk @ 6280' PLUG #1 6388'-6183' Dk Perfs 6224'-6388' 36 SXS CEMENT PBTD 6464'

4-1/2" 10.5# @ 6479' (347 cf cement)

7-7/8" HOLE TD 6479'