Form	9-331
(May	1963)

	Form	app	rove	d.				
	Budge	t B	urea	.u 1	No.	42-	R14	2
PASE	DERIC	MAR						_

(May 1963)	UNITED STATE DEPARTMENT OF THE		SUBMIT IN TRIPLICA (Other instructions on	re- !	Form approved. Budget Bureau No.	42-R1424.
			verse side)	/	DESIGNATION AND S	
	GEOLOGICAL SU	RVEY		I = 14	9-IND. 797	71
SL	INDRY NOTICES AND REF	ORTS ON	WELLS /	6. IF INDI	AN, ALLOTTER OR T	RIBE NAME
(Do not use t	this form for proposals to drill or to deep Use "APPLICATION FOR PERMIT—	en or plug back	to a different reservoir.			
1.		Tot saca propos	uis.,,	7		
OIL GAS WELL WELL	L XX OTHER			7. UNIT A	GREMMENT NAME	
2. NAME OF OPERATOR			· · · · · · · · · · · · · · · · · · ·		3 4 4	
	_			8. FARM C	R LEASE-NAME -	
3. ADDRESS OF OPERA	OIL COMPANY			Galle		
		D	0.1 1 6	9. WELL 1	10.	
4. LOCATION OF WELL	00 Lincoln Tower Bldg	. Denve	r, Colorado 8) = 1	
See also space 17 At surface	below.)	e with any State	requirements	10. FIELD	AND POOL, OR WILD	CAT
	11001 ECT 3 200	01 77.77		Basir	n Dakota	
	1100' FSL and 2000' FWL			11. SEC., 7	r., s., m., or blk. an vey or abba-	Œ
14. PERMIT NO.	I IE Province (Ch				29, T26N,	
14. TERMIT NO.	15. ELEVATIONS (Show		R, etc.)	12. COUNT	Y OR PARISH 13. S	TATE
	6391	.0 GR		San	Juan Ne	w Mexi
16.	Check Appropriate Box To I	ndicate Natur	e of Notice Report of	or Other Date		
	NOTICE OF INTENTION TO:			7 4 5 5	-	
	[]		SUB	SEQUENT-REPORT	(O)Fr	
TEST WATER SHU	T-OFF PULL OR ALTER CASING		WATER SHUT-OFF	XX -	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	= A a	ALTERING-CASING	
SHOOT OR ACIDIZE	ABANDON*	<u> </u>	SHOOTING OR ACIDIZING		ABANDONMENT*	
REPAIR WELL	CHANGE PLANS		(Other)	<u>. 4413 77 </u>		
(Other)			Completion or Reco	OMDIEDON KEAAPI	completion on Well and Log form.)	
	OR COMPLETED OPERATIONS (Clearly state: If well is directionally drilled, give subs	all pertinent deta urface locations :	ills, and give pertinent da	tes, including es	timated date of st	arting any
nent to this work	L) *		ma mastica and tide ve	- cicar depens for	an markers and z	ones perti-
T	3 3 / 63001					3
well dril	led to 6100' KDB, 7-	7/8" hole	e. Ran IES,	CNL and	DIL logs.	· · · · · · · · · · · · · · · · · · ·
D 300 1		_				
Kan 188 J	oints 4-1/2" casing	with stag	ge collar set	at 2120	Set	
					- s = 173 - 1	-
casing at	: 6100' KDB and ceme:	nted in	two stages as	follows	First	
			:	y		
stage: 30	00 sacks 50-50 poz wi	th 10% sa	alt and 2% ge	1. Plug	down at	9:40
A.M. 3-26	-73. WOC, Second stag	ge: Use	d 385 sacks H	alcolite	w/4% gel	•
D. 3		_		- 展出電影電		
Plug down	at 1:15 P.M. 3-26-7	Good	circulation	througho	ut both	
-1	** ** * * * * * * * * * * * * * * * * *			무실수없면		
stages.	Waiting on completion	n unit.		무료일본론		
	STILL BY				. 를 생각했다	
		•	ه فڪ جائي ۾ سين يو			
	/ONLY LE	1	: : :		स्ति विश्वति	
	1072	1	F.PR Soli			
	2 1973					
	MAY	. 1	1			
	/ CON. COM	7	.	3 F4 62		
	MAI CON. COM at the foregoins by brue and borrect				^S a Sušā	
3. I hereby certify the	at the foregoing is true and correct		_	祖身の書名	ទីភូ ការួនទ	
SIGNED LA	they Wattlene II	rre Sr. Pr	oduction Cle	rk DATI	4/26/7	3
(This space for Fed	deral or State office use)					
	/					
APPROVED BY	APPROVAL, IF ANY:	rle		DATI		
COMPARIONS OF A	ALLEOVAL, IS AMI;				11.000 1.000	
					ت د د د د ⊷ د	
					1	
	*See In	structions on R	Reverse Side		د ند ســ	