					V Bu	rm approved. dget Bureau No. 1	004 0125	
Form 3160~5 (November 1983)	DEDAD.	UNITED STAT MENT OF THE		SUBMIT IN TRIPLIC.	n re Ex	pires August 31, 1	1985	
(Formerly 9-331)		AU OF LAND MAI		/ verse mue)	7 I	0-0603-810		
CLIN				WELLS		DIAN, ALLOTTEE OR T		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						Navajo Tribe		
OIL X GAB					7. UNIT	AGREEMENT NAME		
WELL WELL OTHER 2. NAME OF OPERATOR						8. FARM OR LEASE NAME		
Texaco Inc.						Navajo Tribe "AL"		
3. ADDRESS OF OPERATOR						9. WELL NO.		
P.O. BOX EE COrtez, CO.81321 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10 FIEL	4 10. FIELD AND POOL, OR WILDCAR		
See also space 17 below.)						Tocito Dome // /		
At surface RECEIVED						T., R., M., OR BLK. A	MD ()	
JUL 1 5 1985						NAME OF ARMA		
14. PERMIT NO.					Sec.	28, T26N	, R18W N	
		16. BLEVATIONS (Show The The CLAND MANAGEMEN!			l	1		
5698' DF					ISan C		<u>w Mexi</u> co	
16.	Check A	Appropriate Box To	Indicate Natu	re of Notice, Report,	or Other Dat	ła		
NOTICE OF INTENTION TO:						T OF:		
TEST WATER SHUT-O	FF	PULL OR ALTER CASIN	o	WATER SHUT-OFF		REPAIRING WELL		
FRACTURE TREAT SHOOT OR ACIDIZE		MULTIPLE COMPLETE ABANDON*		FRACTURE TREATMENT SHOOTING OR ACIDIZING		ALTERING CASING		
REPAIR WELL		CHANGE PLANS	XX	(Other)	<u> </u>	ABANDON MENT*		
(Other)	(Other) (Note: Report resu Completion or Reco					its of multiple completion on Well appletion Report and Log form.)		
17. DESCRIBE PROPOSED OF proposed work. If nent to this work.)	R COMPLETED O well is direc	PERATIONS (Clearly stationally drilled, give su	te all pertinent de absurface locations	tails, and give pertinent and measured and true			tarting any sones perti-	
				ell because i nuarv. 1985.				
produce. The well was shut-in in January, 1985. Cumulative production 5729 BO, and 18266 MCF Gas. Well to be plugged and abandoned contingent								
			oval (App	roximately 90	days).			
ABANDONMENT PROCEDURE: 1.) Fill hole with mud.								
1.) Fill hole with mud.2.) Spot 25 sxs cement plug across Barker Creek Perfs.								
3.) Spot 20 sxs cement plug @ 5950'.								
4.) Spot 20 sxs cement plug @ 5025'.								
5.) Spot 20 sxs cement plug @ 3750'.						983a.		
6.) * Spot 20 sxs cement plug @ 1650'. 7.) Spot 10 sx surface plug inside 7" csg.					[[]			
		ole marker,			U_{i}		e and	
	_	Comput plu			,	C. D. ST. J.		
,		,	0		· Constitution of the state of	(
						Dist	ž	

(This space for Federal or State office use) APPROVED BY _______CONDITIONS OF APPROVAL, IF ANY: TITLE BLM (6) - NMOGCC (3) - Navajo Tribe -JNH-AJS-ARM

*See Instructions on Reverse Side