

6 BLM 1 File 1 Yates  
**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**BUREAU OF LAND MANAGEMENT**

1 ABO  
SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 17018

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ABO

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

WAW F-  
Undesignated PC

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 28, T26N, R12W, NMPM

12. COUNTY OR PARISH 13. STATE

San Juan NM

P O Box 208, Farmington, NM 87499

RECEIVED

OCT 27 1986

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

990' FNL - 990' FWL

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6056' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

Plan to plug & abandon well as follows:

- 1.) Fill 2-7/8" OD, 6.5#, 8 Rd EUE J-55 tubing for casing from  
P.B.T.D. 1170' to surface using 35 sx (41cf) class "B" neat cement.
- 2.) Install permanent dry hole monument.
- 3.) Fill all pits.
- 4.) Clean well location of all equipment, pipe, junk and trash.
- 5.) Restore surface.
- 6.) Cut off tie-downs.

8. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan

TITLE Geologist

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

RECEIVED  
OCT 30 1986  
OIL CON. DIV.  
DIST. 3  
APPROVED  
DATE 10-24-86  
OCT 29 1986  
DATE [Signature]  
FOR AREA MANAGER  
FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

NMCCC