

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other instructions on reverse side)

Budget Bureau No. 42-R142a

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Kirby Exploration Company

3. ADDRESS OF OPERATOR
P.O. Box 1745, Houston, Texas 77001

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
980' FNL and 1350' FWL

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6263 GL

5. LEASE DESIGNATION AND SERIAL NO.
NM 0559973

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Grigsby Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT
WAW Picture Cliff Extension

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
Sec 9 - 26N - 13W

12. COUNTY OR PARISH
San Juan
13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Well was plugged and abandoned as follows:
1. Set 50 sacks cement plug from 1300 to total depth 1551.
 2. Set 25 sacks cement plug from 450 to 550'.
 3. Set 70 sacks cement plug from 50' to 250'.
 4. Set 5 sacks cement plug in top of surface pipe.
 5. Cut off surface pipe 3' below ground level.
 6. Dry hole marker will not be installed.
 7. Well plugged and abandoned 3:00 p.m. 6-11-76.

JUN 17 1976
U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct
SIGNED William T. Jones TITLE Agent DATE 6-14-76

(This space for Federal or State office use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side