Form 9-331 (May 1963)	UNITED STATES  SUBMIT IN TRIPLICATE  DEPARTMENT OF THE INTERIOR (Other instructions on re-  GEOLOGICAL SURVEY			Form approved. Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)				NM 0559973  6. IF INDIAN, ALLETTEE OR TRIBE NAME	
<u>v</u> .	se "APPLICATION FOR PERM	IIT—" for such proposals.)	different reservoir.		
OIL GAS WELL A OTHER  2. NAME OF OPERATOR				7. UNIT AGREEMENT NAME	
Kirby Exploration Company 3. ADDRESS OF OPERATOR				8. FARM OR LEASE NAME Grigsby Federal	
P.O. Box 1745, Houston, Texas 77001  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  At surface				9. WELL NO.  1 10. FIELD AND POOL, OR WILDCAT	
980' FNL and 1350' FWL				WAW Picture Cliff Extension 11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA	
14. PERMIT NO.	15. ELEVATIONS (	15. ELEVATIONS (Show whether DF, RT, GR, etc.)			- 13W
16.	626	3 GR		San Juan	New Mexico
		TR.  SH  (O  ate all pertinent details, and in  subsurface locations and in	TER SHUT-OFF ACTURE TREATMENT OOTING OR ACIDIZING ther) (Note: Report results of Completion or Recomplet)	ULL DEDOLE BUUL PUG LVG LVG	ISING TT*
Well will be plugged and abandoned as follows:  1. Spot 50 sacks cement plug from 1300' to total depth of 1550'.					· · · · · · · · · · · · · · · · · ·
2. Spot 25 sacks cement plug from 450 to 500'.					* * * * * * * * * * * * * * * * * * *
3. Spot 70 sacks cement plug from 250' to 50'.					
4. Cut off surfac	ce pipe 3' below gr	round level and	spot 5 sacks ce	ment plug	
No drill hole marker will be installed.				A water to the said.	
				JUN 1.4	1976 

Olcal

\*See Instructions on Reverse Side