

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM 17781
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 420, Farmington, NM 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FNL & 990' FEL	8. FARM OR LEASE NAME Paul Revere
	9. WELL NO. 202
	10. FISH AND POOL, OR WILDCAT Wildcat WAW FRT. PC
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T26N, R13W, NMPM
14. PERMIT NO.	12. COUNTY OR PARISH San Juan
15. ELEVATIONS (Show whether DF, ST, GR, etc.) 6094' GR	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐  
Recomplete ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

RECEIVED

OCT 2 1990

OIL CON. DIV.,  
DIST. 3

Swab test Pictured Cliffs to check production. If Pictured Cliffs is not economical, proceed as follows:

Set cast iron bridge plug above Pictured Cliffs perforations at 1175'. Pressure test casing. Perforate Fruitland Coal 1152-68' with 2 shots/ft. Stimulation will depend on results of test.

18. I hereby certify that the foregoing is true and correct

SIGNED John Alexander  
John Alexander

TITLE Operations Manager

DATE 9-13-90

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

APPROVED

SEP 27 1990

Ken Townsend

FOR AREA MANAGER

\*See Instructions on Reverse Side