Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

CHAIDDY NOTICES	AND DEDODTE ON WELLS	NM1 1 0 8 9
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil		8. Well Name and No. TENNECO FEDERAL NO.1 9. API Well No.
3. Address and Telephone No. 12221 MERIT DRIVE, SUITE 500 DALLAS, TX 75251 (214)701-8377 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 800' FSL & 800' FML, SEC. 8 T26N R12W		10. Field and Pool, or Exploratory Area WAW FARMINGTON 11. County or Parish, State SAN JUAN CO., NEW MEXIC
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION	TYPE OF ACTION	4
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
(ATTACHED)	JUN 41993 OIL CON. DIV. LDIST. 3	RECEIVED 83 JUN -1 AM 11: 36 070 FARMINGTON, NM
14. I hereby certify that the foregoing is true and correct Signed	Title District Manager	Date 5/27/93
Approved by	Tide	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States in Vail fraudulon statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

ACDIOTOTOT MANAGE

APPHOVED

Abandonment Procedure Tenneco Federal No. 1 800' FSL & 800' FWL SW 1/4 SW 1/4 Sec. 8 T-26N, R-12W San Juan Co., New Mexico

Projected Start Date: June 16, 1993

- 1. MIRU
- 2. POH w/production equipment
- 3. Circulate w/ CI fluid.
- 4. Set CIBP @ 500'
- 5. Sqeeze perfs 450'-466' w/ 15 sx.
- 6. Spot cement (15 sx class B cement) from 500' to surface.
- 7. RDMO.
- 8. WOC
- 9. Cut off wellhead/casing to 6' below grade.
- 10. Remove all production equipment from location.
- 11. Reseed location w/native grasses.

100 Quet su lace (calc.) 7 -Tenneco Federal No.1 800'FSL 800'FWL Sec. 8 TZGN, RIZW San Juan Co., NM BEFORE 51/2" (sg @ 31.6' 450-66' (2spf) 568-70' (4spf) 1164-68' (21/8" glass jets 25pf) 1170-74' (21/8" glass jets 25pf) 2 78" csg @ 1344'

TD:1351'

