UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED Budget Bureau Mo. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

JUNEAU AND THE STATE OF THE STA		Į.	I-149-IND-7971	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		6. If Indian, Allottee o	or Tribe Name	
*		7. If Unit or CA, Agr	eement Designation	
1. Type of Well Oil Well Gas Well Other		8. Well Name and N	о.	
2. Name of Operator	Attention:	Nav	aio 2E	
Amoco Production Company	Beth Gonzalez	9. API Well No.		
3. Address and Telephone No.			3004524789	
P.O. Box 800, Denver, Colorado 80201 (303) 830-5651		10. Field and Pool, o	10. Field and Pool, or Exploratory Area	
4. Location of Weil (Footage, Sec., T., R., M., or Survey Description)			Basin Dakota	
1660 FSL 870 FWL	Sec. 28 T 26N R 11W	11. County or Parish San J		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Attering Casing Other	Change of Plans New Construction Non-Routine Fracturi Water Shut-Off Conversion to Injecti Dispose Water (Note: Report results of multiple or Recompletion Report and Log form	on :	
If you have any questions please call B		SEIVED	RECEIVE BLM 94 JUL 28 AM	
Λ	() () ()	ON. DIV. OT. 2	AM IO: 18	
14. I hereby certify that the foregoing is trul and correct Signed	M2ale2 Title E	Business Analyst	07-27-1994	
(This space for Federal or State office use) Approved by	Title		Date	
Conditions of approval, if any:				
Title 18 U.S.C. Section 1001, makes it a crime for any person kn any matter within its jurisdiction.	owingly and willfully to make to any department or agency of the	United States any faise, ficticions, onth	uout nt statements representations as t	

PXA Procedures Navajo 2E

- Remove lift equipment.
- Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. POOH with 2 3/8" tbg. RIH with tbg and cement retainer, set retainer at 5775'. Squeeze perfs at 5830' to 5840' with 22.277 cuft cement. Pull out of retainer and spot 2 sx cement on top of retainer. Load hole with 9ppg mud to 4825'.
- 5. Load hole to surface with 647.756 cuft cement.
- 6. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or state requirements.
- 7. Turn over to John Schwartz for reclamation.
- 8. Rehabilitate location according to BLM or state requirements.

NAVAJO 002E 244
Location — 28L— 26N—11W
SINGLE dk
Orig.Completion — 3/81
Last File Update — 1/89 by BCB

