

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals

5. Lease Designation and Serial No.
NOO-C-14-20-3629

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

8. Well Name and No.
Chaco Plant #22

2. Name of Operator
J. K. Edwards and Assoc.

9. API Well No.
30-045-24908

3. Address and Telephone No. **C/O Walsh Engineering & Production Corp.**
7415 East Main Farmington, NM 87402 505-327-4892

10. Field and Pool, or Exploratory Area
S. Gallegos Ft Sand - PC

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1050' FNL & 1080' FEL, Sec. 24, T26N, R12W, Unit A

11. County or Parish, State
San Juan County, NM.

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

J.K Edwards plans to Plug and Abandon this well according to the attached procedure.

RECEIVED
APR 11 1997

OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed Paul C. Thompson (Paul C. Thompson) Title Agent Date 03/28/97

(This space for Federal or State office use)

Approved by /S/ Duane W. Spencer
Conditions of approval, if any

Title _____ Date APR - 9 1997

Walsh Engineering and Production

**Plug and Abandon Procedure for
J.K Edwards and Associates
Chaco Plant #22**

Location: NE/4 Sec 24 T26N R12W
San Juan County, NM


Date: March 28, 1997

Field: S. Gallegos Fruitland Sand & PC
Surface: Navajo Allotted
Minerals: NOO-C-14-20-3629

Elev: GL 6020'
PBSD 1249'

Procedure:

1. MOL and RU P&A rig. Hold safety meeting.
2. Blow well down and ND tubing head.
3. Release donut and TOH with 1-1/4" tubing.
4. Pump plug #1 50 sx (59 cu. ft.) of cement down 2-7/8" tubing from PBSD at 1249' to surface. Drop 30 ball sealers in the first 10 sx of cement. Hold pressure on cement for 1 hour. Maximum pressure is 500#.
5. Cut off wellhead below surface casing. Install P&A marker. Rig down and release rig.
6. Clean location and restore as per BLM requirements.



Paul C. Thompson, P.E.

COPIES
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100


J. K. EDWARDS & ASSOC.

CHACO PLANT #22

NE/NE 24 T26N R12W

CURRENT STATUS

P#A STATUS



8 3/4" HOLE
7" @ 86'
CMT W 35 SK

1 1/4" TUBING
AT 1065'

1052

15 PERFS


1178

PBTD @ 1249

5" HOLE

2 7/8 @ 1275

CMT W 230 SK



Plug #1
50 SK (59 cu ft)
W/ 30 BALL SEALERS

1052

1178

CHACO PLANT #22