For (I	m 9- Feb. 19	331 a 351)	
			 •

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Offic	. Ŝ	ante	Fe	/
Lease No.	076	105		
1 68 F		77 :		

NOTICE OF INTENTION TO DRILL		ENT REPORT OF WATER SHUT-OFF		
OTICE OF INTENTION TO CHANGE	PLANSSUBSEQUE	NT REPORT OF SHOOTING OR ACIDIZING	l l	
OTICE OF INTENTION TO TEST WAT	ILK ONO! OF THE PROPERTY OF TH	NT REPORT OF ALTERING CASING	1	
OTICE OF INTENTION TO RE-DRILL	- O	NT REPORT OF RE-DRILLING OR REPAIR	1 3	
OTICE OF INTENTION TO SHOOT O		ENT REPORT OF ABANDONMENT	1	
IOTICE OF INTENTION TO PULL OR		ENTARY WELL HISTORY		
HOTICE OF INTENTION TO ABANDON	N WELL			
(INDIC	ATE ABOVE BY CHECK MARK NATURE OF REF	ORT, NOTICE, OR OTHER DATA)		
.M. Federal "J"		December 20		
ell No. 2 is loca	ated 790 ft. from $\begin{Bmatrix} \mathbf{R} \\ \mathbf{S} \end{Bmatrix}$ line a	and 790 ft. from $\left\{\begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix}\right\}$ line of $\left\{\begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix}\right\}$	sec. 23	
w/lı 3w/lı 5ec. 23	778 136 (Twp.) (Range)	(Meridian)		
(½ Sec. and Sec. No.)	flam Imam	Hew Mexico		
(Field)	(County or Subdivision)	(State or Territory)		
مناهدها المتعدد		i lengths of proposed casings; indicate indic	ting jobe, centre	
e have plugged & ab	to objective sands; show sizes, weights, and ing points, and all other importanent this well as fol	lovs:		
e have plugged about a conserved plug over G 2h2', placed h0 sx, sipe 320' to 270'.	andoned this well as fol		cag at	
ie have plugged & ab	andoned this well as fol	lows: 10 to 4975', shot off highted 20 sacks, plug bim of to surface. Set he pip	ceg at surface e marker	
e have plugged about accept a large and a large and a large a	andoned this well as fol allup zone, 20 sacks, 52 plug 12k2' to 1000'. P Placed ho sacks, plug 90	lows: 10 to 1975', shot off high	ceg at surface marker	
io have plugged abordered plug over G. 2h2', placed ho ax, sipe 320' to 270'.	andoned this well as fol allup zone, 20 sacks, 52 plug 12k2' to 1000'. P Placed ho sacks, plug 90	lows: 10 to 4975', shot off his laced 20 sacks, plug btm to surface. Set his pip	ceg at surface marker	
iqueezed plug over 3.212', placed ho ax, sipe 320' to 270'.	endoned this well as fol- allup zone, 20 sacks, 52 plug 12k2' to 1000'. P Placed hO sacks, plug 90 ork must receive approval in writing by the i-Continent (11 Company)	lows: 10 to 1975', shot off his laced 20 sacks, plug bta to surface. Set his pip DEC 22	ceg at surface marker	
oneszed plug over G 2h2', placed h0 sx, ipe 320' to 270'. ell abandoned.	endoned this well as fol- allup zone, 20 sacks, 52 plug 12k2' to 1000'. P Placed hO sacks, plug 90 ork must receive approval in writing by the i-Continent (11 Company)	lows: 10 to 4975', shot off his laced 20 sacks, plug btm to surface. Set his pip	ceg at surface marker	
oneszed plug over G 2h2', placed h0 sx, ipe 320' to 270'. ell abandoned.	endoned this well as fol- allup zone, 20 sacks, 52 plug 12k2' to 1000'. P Placed ho sacks, plug 90 ork must receive approval in writing by the i-Continent (11 Company)	lows: 10 to 1975', shot off his laced 20 sacks, plug bta to surface. Set his pip DEC 22	ceg at surface marker	