

GOVERNOR  
JACK M. CAMPBELL  
CHAIRMAN

State of New Mexico  
Oil Conservation Commission



LAND COMMISSIONER  
GUYTON B. HAYS  
MEMBER

1000 RIO BRAZOS RD.  
AZTEC

April 13, 1965

W. H. H.		
J. B. A.		
S. F.		
REC. APR 15 1965		
J. A. G.		
FILE		

STATE GEOLOGIST  
A. L. PORTER, JR.  
SECRETARY - DIRECTOR

Southwest Production Company  
1126 Mercantile Securities Building  
Dallas, Texas

Attn: Mr. J B. Avant, Agent


Dear Mr. Avant:

I am returning three copies of Form C-103, Subsequent Report of Plugging, for your #1 Collier Federal well located in the SW $\frac{1}{4}$  Section 18-27N-12W.

I have reviewed earlier Federal reports filed for this well and have determined that there was an attempted workover in the Dakota Formation and I presume that these attempts failed. I also presume from these earlier reports that all deeper perforations were squeezed and the cement plugs were left in the casing above the top of the Dakota Formation. However, your final plugging report should briefly review the condition of the entire hole so far as position of the cement plugs within the casing and the position of the cement outside the casing which was left in the hole. Also, please indicate whether or not the pits were filled and the location levelled.

As this well is located on Federal Land the primary approval must come from the U.S.G.S. I presume that they have approved your plugging procedure.

Yours very truly

  
Emery C. Arnold  
Supervisor, District #3

ECA:ks

cc: U.S.G.S., Farmington, N.M.