

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO 1000 RIO BRAZOS ROAD - AZTEC GOVERNOR
DAVID F. CARGO
CHAIRMAN

LAND COMMISSIONER ALEX ARMIJO MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

March 14, 1969

Kingwood Oil Co. 100 Park Avenue Building Oklahoma City, Oklahoma 73102

Attn: Mr. Ben Spain, Chief Production Clerk

Re: Remedial Action, Kingwood Oll Co., Knauff #1, A-13-27N-10W

Dear Mr. Spain:

Will you please file Federal Form 9331-A, Sundry Notice and Report on Wells, relative to the remedial work which was performed on the above well in 1966?

I have your letter of January 24, 1969, which states that damage occurred to the well head and stating that a packer had been run in the well.

The Sundry Notice filed should include the following information:

- 1. Any tests conducted to determine casing failure or to indicate the condition of the casing down hole.
- 2. The size and amount of tubing re-run in the hole and the type packer installed and the depth at which the packer was set.
- 3. Any other information on work performed which materially effects the present condition of the well.

The above report should be filed in quatruplicate with the United States Geological Survey Office in Farmington, New Mexico.

Thank you.

Yours very truly,

Emery C. Arnold Supervisor, District #3

ECA:mc

cc: USGS, Farmington, New Mexico
Oil Conservation Commission, Santa Fe, New Mexico