Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RECEIVED

FORM APPROVED
Budgét Bureau No. 1004-0135
Expires: March 31, 1993
/ <u></u>

	BLM MAIL ROOM	
SUNDRY NOTICES.	AND REPORTS ON WELLS	5. Lease/Designation and Serial No.
	rill or to deepen or reentry was afficient reserved:	36 / SF-077382
	OR PERMIT - " for such proposals	6. Il Indian, Allottes or Tribe Name
USO ATTECATION FO		
	070 FARMING I ON, I	MM
		7. If Unit or CA, Agreement Designation
1. Type of Well OI Well Well Other		
Well Other 2. Name of Operator		8. Wall Name and No.
Amoco Production Company	Attention:	Hargrave A #2
	Gail M. Jefferson, Rm 1295C	9. API Well No.
J. Address and Telephone No.		3004506733
P.O. Box 800, Denver, Colorado 80201	(303) 830-6157	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Descrip	ption	Fulcher Kutz PC
0001 FN: 16501 ===	Sec 0 T 27N B 10M Mark B	11. County or Perish, State
890' FNL 1650' FEL	Sec. 9 T 27N R 10W Unit B	
CUECK ADDRODULES		San Juan New Mexico
12. CHECK APPROPRIATE BO	X(s) TO INDICATE NATURE OF NOTIC	E , REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	TION
X Notice of Intent	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Beck	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing Other	Conversion to Injection
		Dispose Water ta: Report results of multiple completion on Well Completion or
	Rec	ompletion Report and Log form.)
per the attached.	ests permission to plug and abando stions please contact Carolanne Wy ive concerns.	yett at (303) 830-5578 or Gail
		$\psi_{ij}^{\dagger} \psi_{ij}^{\dagger} = \mathcal{D}_{ij}^{\dagger}$
,		A Company of the Comp
Signed Law Ch.	usur Title Sr. Admin. S	Staff Asst 000 11/28/95
his space for Federal or State office use)		APPROVED
Approved by	Title	DEC 03 1995
Cenditions of approvel, if eny:	Allerian	
	NMOCD /	/ DISTRICT MANACER

Hargrave A #2
Orig. Comp. 3/50
TD = 2062', PBTD = 2036'
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 1/16" tbg. RIH with tbg and cement retainer. Set retainer at 1948'. Test casing integrity to 500#. Squeeze perfs at 1998' to 2029' with 37 cuft of cement. Pull out of retainer and spot cement plug to 1900' with 5 cuft cement. RIH with pipe cutters and cut 3 1/2" pipe at TOC. Pull pipe. Run short string CBL to determine TOC.
- 4. Depending on TOC be sure the following intervals have 100' cement inside and outside csg.

Fruitland Coal at 1605' Ojo Alamo at 1110' 146 to surface

- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Turn over to John Schwartz for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

LEASE: HARGRAVE "A"

WELL NO.:

KB LLEV.: ____6101

LOCATION: 890' FNL, 1650' FEL

Sec. 9, 27N, 10W

San Juan Co., N.M.

9 5/8" O.D. 36 LB. J-55 CSG. Set @ 96 w/ 75 sx.

Completed 3-9-50. Open hole section 1988-2063 shot w/170 qts. SNG. Initial test 686 NCF/D.

Casing repair 3-18-65. 3 1/2" csg. set @ 2062. Perf'd 1998-2029 w/2 HPF. Frac'd w/30,000 gal water, 22,500 lb. sand. Max rate 39 BPM. Prod. tested 90 MCF/D against 110 # 11ne pres.

2 " TBG. Set @ 2009' 2 1/6" 3.25 # JIS smls

5 1/2" O.D. 14 LB. J-55 CSC. Set @ 1988 | w/ 100 sx. 1998

2 HPF

2029

2036 PUTD

2062 T.D. 3 1/2" O.D. 5.75 LB. 11-40 CSG. Set @ 2062 'w/ 150 sx.

circid