Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on re-

Form approved.

Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

| | CE | OLOGICAL SURV | EY | 1 31 0 | 78050 | OR MUTER NAME | |
|--|---|--|---|---|--|---------------------|--|
| | | | | 6. IF I | INDIAN, ALLOTTEE | UR TRIDE DAME | |
| SUNI | ORY NOTIC | ES AND KEPOI | RTS ON WELLS or plug back to a different reserv | oir. | | | |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) | | | 7. UNI | 7. UNIT AGREEMENT NAME | | | |
| OIL GAS [| T | | · | _ | | | |
| WELL WELL X OTHER NAME OF OPERATOR | | | | 2 | 8. FARM OR LEASE NAME | | |
| El Paso Natural Gas Company | | | | | Turner Hughes 9. WELL NO. | | |
| ADDRESS OF OPERATOR | | | | | (P & A) | | |
| P 0 Box 99 | 90. Farming | gton, NM 8740 | | | IELD AND POOL, OR | WILDCAT | |
| LOCATION OF WELL (R See also space 17 belo | eport location cle | early and in accordance w | With State education | | ıth Blanco | | |
| At surface | | | | 11. s | EC., T., R., M., OR E SURVEY OR AREA | LK. AND | |
| 0001N 7001 | C | | | | SUBVEY OF ABEA 3, T-27- | N, R-9-W | |
| 990'N, 790' | E . | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | N.N | M.P.M. | 13. STATE | |
| PERMIT NO. | | 15. ELEVATIONS (Show w | vhether DF, R. GK, etc. | ı | n Juan | New Mexico | |
| 1200012 | | 6185' GL | | | | THEM THEME | |
| | Charle An | propriete Box To Ind | licate Nature of Notice, Re | eport, or Other l | Data | | |
| | NOTICE OF INTENT | | ł | SUBSEQUENT R | EPORT OF: | | |
| | | r | WATER SHUT-OF | | REPAIRING ' | WELL | |
| TEST WATER SHUT-C | '" i1 | OULL OR ALTER CASING | FRACTURE TREAT | 1 1 | ALTERING C | I Y I | |
| FRACTURE TREAT | | ABANDON* | SHOOTING OR AC | CIDIZING | ABANDONME | NT* A | |
| SHOOT OR ACIDIZE BEPAIR WELL | | CHANGE PLANS | (Other) | teport results of mu | altiple completion | on Well | |
| (Other) | | | Completio | on or Recompletion | Report and Log 10 ding estimated da | te of starting any | |
| | | | | | | | |
| 7. DESCRIBE PROPOSED Of proposed work. I nent to this work. | OR COMPLETED OFE | erations (Clearly state alonally drilled, give subsu | Completion | d true vertical dept | ths for all market | | |
| nent w ans worm | • | | | | ths for all market | | |
| nent w dis worm | was Plugged | d and Abandoned | l in the following π | manner: | | | |
| nent w ans worm | was Plugged Spotted 50 | d and Abandoned O sk cement plug | f in the following f f in the open hole. | nanner: Pulled tub | oing. | · | |
| This well w | was Plugged Spotted 50 | d and Abandoned O sk cement plug | l in the following π | nanner: Pulled tub | oing. | | |
| This well v | was Plugged Spotted 50 Pressured | d and Abandoned O sk cement plug up on 5 1/2" o | l in the following m g in the open hole. casing, circulated h | nanner: Pulled tub hole and won | oing. | | |
| This well well of the control of the | was Plugged Spotted 50 Pressured Shot off | d and Abandoned 0 sk cement plug up on 5 1/2" of casing at 1478 | d in the following m g in the open hole. casing, circulated b and pulled casing. | nanner: Pulled tub hole and wor | oing. | | |
| This well work of the control of the | Spotted 50 Pressured Shot off Spotted 6 | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478" | I in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over | nanner: Pulled tub hole and wor . Ojo Alamo. | oing. rked casing | . | |
| This well work of the control of the | Spotted 50 Pressured Shot off Spotted 6 | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478" | l in the following m g in the open hole. casing, circulated h and pulled casing. | nanner: Pulled tub hole and wor . Ojo Alamo. | oing. rked casing | . | |
| This well work of the control of the | Spotted 50 Pressured Shot off Spotted 6 Spotted 2 Spotted a | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478" | I in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over | Pulled tub hole and wor Ojo Alamo. | oing. rked casing | Abandonment | |
| This well work of the control of the | Spotted 50 Pressured Shot off Spotted 6 Spotted 2 Spotted a | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478" | I in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over | Pulled tubhole and work Ojo Alamo. installed | oing. rked casing a Plug and | Abandonment | |
| This well well of the control of the | Spotted 50 Pressured Shot off Spotted 6 Spotted 2 Spotted a | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478" | I in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over | Pulled tub hole and wor Ojo Alamo. installed | oing. rked casing a Plug and | Abandonment | |
| This well work of the control of the | Spotted 50 Pressured Shot off Spotted 6 Spotted 2 Spotted a marker. | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 14785 5 sk cement plu 0 sk cement plu 10 sk cement plu | d in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over ug at 102'. plug at surface and | Pulled tubhole and work Ojo Alamo. Installed | oing. rked casing a Plug and MAR 2 1 19 | Abandonment ED 75 | |
| This well work of the control of the | Spotted 50 Pressured Shot off Spotted 6 Spotted 2 Spotted a marker. | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478 5 sk cement plu 0 sk cement plu 10 sk cement plu 10 sk cement | I in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over | Pulled tubhole and work Ojo Alamo. Installed | oing. rked casing a Plug and MAR 24 19 GEOLOGICAL SE | Abandonment ED 75 | |
| This well v 02-26-75 02-27-75 02-28-75 03-01-75 | Spotted 50 Pressured Shot off Spotted 6 Spotted 2 Spotted a marker. | d and Abandoned 0 sk cement plug up on 5 1/2" c casing at 1478 5 sk cement plu 0 sk cement plu 10 sk cement plu 11 sk cement plu 12 sk cement plu 13 true and correct | d in the following mag in the open hole. casing, circulated has and pulled casing. ug at stub and over ug at 102'. plug at surface and | Pulled tubhole and work Ojo Alamo. Installed | oing. rked casing a Plug and MAR 2 1 19 | Abandonment | |