

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

SF 078716

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hubbell

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Fulcher Kutz PC

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 29, T-28-N, R-10-W
N.M.P.M.

12. COUNTY OR PARISH 13. STATE

San Juan NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below
At surface

1650'S, 1850'E

14. PERMIT NO.

15. ELEVATIONS (SHOW WHETHER OF, TO, OR, ETC.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

It is intended to plug & abandon this well in the following manner:

MOL&RU. Install BOP. Pull 1" line pipe. TIH w/2 3/8" work string. Circ. w/9# mud (25 sx gel/100 bbl). Tag TD. Spot 50 sx Cl B cmt w/2% CaCl plug (59 cf) from 2085-1940'. WOC. Tag top of plug (1940'). Pull tbg to 1799'. Spot 12 sx (14 cf) plug 1799-1699' to cover Fruitland. TOOH w/tbg. Press test csg to 500#. Perf 2 squeeze holes @ 1179'. TIH w/tbg to 1179'. Mix & pump 77 sx (91 cf). Pressure displace 44 sx (52 cf) through squeeze holes. Spot 33 sx (39 cf) 1179-850' to cover from 50' below Kirtland top to 50' above Ojo Alamo top. WOC. Perf 2 squeeze holes @ 95'. Circ. cement back to surface through squeeze holes. Use 110 (132 cf) sx. Cut off wellhead. Install dry hole marker w/10 sx (12 cf) cmt.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Clerk

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE 4-10-87
AS AMENDED

DEC 15 1987
AREA MANAGER

*See Instructions on Reverse Side