

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1660' FEL, 1495' FSL, Sec. 28, T-28-N, R-10-W, NMPM

5. Lease Number  
SF-077383A

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

8. Well Name & Number  
Kutz Deep Test #3

9. API Well No.  
30-045-29930

10. Field and Pool  
Fulcher Kutz PC

11. County and State  
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment

Type of Action

☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other -  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut off  
☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to plug and abandon the subject well according to the attached procedure and wellbore diagram. The deadline to submit this procedure is 8/31/2001.

2001 SEP 31 AM 9:45



14. I hereby certify that the foregoing is true and correct.

Signed Tammy Wimsatt Title Regulatory Supervisor Date 8/30/01  
TLW

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date 9/18/01

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

44440

## PLUG AND ABANDONMENT PROCEDURE

### Kutz Deep Test #3

AIN #80878301

Fulcher Kutz Pictured Cliffs

1495' FSL and 1660' FEL, Section 28, T28N, R10W

San Juan County, New Mexico, API #30-045-2993


Lat: 36 – 37.8036' / Long: -107 – 53.8122'

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

All cement will be ASTM Type II, mixed at 15.6 ppg with a 1.18 cf/sx yield.

1. Test rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary. ND wellhead and install cementing valve.
2. Open bradenhead valve. Establish rate down 2-7/8" casing with 20 bbls water, record pump rate and pressure. Monitor bradenhead for flow. If no flow or blow, then pump 6 7/8" RCN balls in additional water and monitor pressure, rate and volumes pumped, to confirm perforations are taking water and there is not a casing leak. If the bradenhead flows water or there are other indications of a casing leak, then MO and RU pulling unit and use 1-1/4" IJ tubing workstring to set plugs the well.
3. **Plug #1 (Pictured Cliffs perforations and Fruitland, Kirtland and Ojo Alamo tops, 2168' - Surface')**: Establish rate into Pictured Cliffs perforations with water. Mix and pump 80 sxs cement (long plug, 30% excess) down 2-7/8" casing, do not displace. Shut in the master valve. WOC. Open valve and determine where the cement is. If necessary, rig up wireline truck and tag cement. Fill with cement as necessary.
4. ND cementing valve and cut off wellhead. Fill casing and annulus with cement as necessary. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Recommended:

 8-30-01  
Operations Engineer


Approval:

 8-30-01  
Drilling Superintendent

Contacts: Operations Engineer Joe Michetti  
Pager: 564-7187  
Office - 326-9764

Sundry Required: ☒ YES ☐ NO

Approved:

  
Regulatory Approval

# Kutz Deep Test #3

Current

AIN #80878301

Fulcher Kutz Pictured Cliffs

SE, Section 28, T-28-N, R-10-W, Rio Arriba County, NM

API # 30-045-2993

Lat: 36 - 37.8036'/Long: -107- 53.8122'

Today's Date: 08/28/01

Spud: 05-27-99

Completed: 06-10-99

Elevation: 6124' GL  
6136' KB

7-7/8" hole

Circulated 13 bbls Cement to Surface

5-1/2" 15.5#, K-55 Casing set @ 129'  
Cmt with 59 cf (Circulated to Surface)

Ojo Alamo @ 1075'

Kirtland @ 1214'

Fruitland @ 1880'

Pictured Cliffs @ 2114'

Pictured Cliffs Perforations:  
2117' - 2168' (15 holes)

PBTD 2298'

4-3/4" hole

TD 2317'

2-7/8" 6.4#, J-55 Casing set @ 2309'  
Cement with 402 cf  
Circulated Cement to Surface

# Kutz Deep Test #3

Proposed P&A

AIN #80878301

Fulcher Kutz Pictured Cliffs

SE, Section 28, T-28-N, R-10-W, Rio Arriba County, NM

API # 30-045-2993

Lat: 36 - 37.8036'/Long: -107- 53.8122'

Today's Date: 08/28/01

Spud: 05-27-99

Completed: 06-10-99

Elevation: 6124' GL  
6136' KB

7-7/8" hole

Circulated 13 bbls Cement to Surface

5-1/2" 15.5#, K-55 Casing set @ 129'  
Cmt with 59 cf (Circulated to Surface)

**Plug #1: 2168' – Surface**  
Cement with 80 sxs  
(long plug, 30% excess)

Ojo Alamo @ 1075'

Kirtland @ 1214'

Fruitland @ 1880'

Pictured Cliffs @ 2114'

Pictured Cliffs Perforations:  
2117' – 2168' (15 holes)

PBTD 2298'

4-3/4" hole

TD 2317'

2-7/8" 6.4#, J-55 Casing set @ 2309'  
Cement with 402 cf  
Circulated Cement to Surface