Form 3160-5 (August 1999)

1. Type of Well

2. Name of Operator

3a. Address P.O. BOX 3092

HOUSTON, TX 77253

TYPE OF SUBMISSION

☐ Final Abandonment Notice

■ Notice of Intent

□ Subsequent Report

Oil Well S Gas Well Other

AMOCO PRODUCTION COMPANY

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 31 T28N R12W Mer NESE 790FSL 890FEL

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FO <b>K</b> M APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

Do not use the	NOTICES AND REPO is form for proposals to II. Use form 3160-3 (AP	5. Lease Serial No. I-149-IND-8478  6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	PLICATE - Other instruc	ctions on reverse side.	OCT 2001	7. If Unit or CA/Agre	ement, Name and/or No.
S Gas Well □ Ott	ner			8. Well-Name and No. GALLEGOS CANYON UNIT 177	
rator RODUCTION COM		Contact: CHERRY HLAVA E-Mail: hlavacl@bp.com		9. API Well No. 30-045-06966	
3092 I, TX 77253		3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700		10. Field and Pool, or Exploratory BASIN DAKOTA	
Vell (Faotage, Sec., T., R., M., or Survey Description) BN R12W Mer NESE 790FSL 890FEL				11. County or Parish, and State SAN JUAN COUNTY, TX	
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA
SUBMISSION		TYPE OF ACTION			
Intent  nt Report  andonment Notice	□ Acidize       □ Deepen         □ Alter Casing       □ Fracture Treat         □ Casing Repair       □ New Construction         □ Change Plans       ☑ Plug and Abandon         □ Convert to Injection       □ Plug Back		☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal		☐ Water Shut-Off ☐ Well Integrity ☐ Other

□ Convert to Injection □ Plug Back □ Wa 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Amoco Production Company requests permission to plug and abandon the subject well as per the attached procedure.

Should you have any technical questions please contact Allen Kutch @281-366-7955. For administrative concerns please contact Cherry Hlava @281-366-4081

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #7293 verified by the BLM Well Information System  For AMOCO PRODUCTION COMPANY, sent to the Farmington  Committed to AFMSS for processing by Lucy Bee on 09/21/2001 ()				
Name (Printed/Typed) CHERRY HLAVA	Title AUTHORIZED REPRESENTATIVE			
Signature	Date 09/20/2001			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved By	Title Date 10/23/01			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# SJ Basin Well Work Procedure

Well Name:

**GALLEGOS CANYON UNIT #177** 

Version:

Date: **SEPTEMBER 19, 2001** 

**Budget:** 

Repair Type: **PLUG & ABANDON** 

**SAP Code:** 

### Objective: P&A WELL

- 1. TOH and strap 5795' 2 3/8".
- 2. Set cement plugs.
- Cut off wellhead & install dry hole marker.

#### Pertinent Information:

Location:

T28N-R12W-Sec31

API#:

30-045-06966

County:

San Juan New Mexico

FlacWell: Engr:

State: Horizon:

Basin Dakota

## Procedure:

- 1. Check anchors. MIRU.
- Check and record tubing, casing, and bradenhead pressures.
- Blow down well. If necessary, kill with fresh water.
- 4. Nipple down WH. NU BOPs. Pressure test to 500 psi.
- 5. TOH and strap 5795' of 2 3/8" tbg.
- RU wireline and set 4 1/2" CIBP at 5800'. TIH with tbg open ended to 5800'.
- 7. Pressure test csg to 500 psi for 15 minutes. Plug #1 (5700' 5800'), balance 8 sx Cl. B cement inside csg. PUH to 4935'.
- 8. Plug #2 (4785' 4935'), balance 12 sx inside casing. PUH to 2230'.
- 9. Plug #3 (2080' 2230'), balance 12 sx inside casing. PUH to 1325'.
- 10. Plug #4 (1175' 1325'), balance 12 sx inside casing. PUH to 418'.
- 11. Plug #5 (0' 418'), mix 32 sx to circulate good cement to surface. POH.
- 12. ND BOP & dig cellar. Cut off wellhead and top off casings as needed.
- 13. RD rig. Remove deadmen. Install dry hole marker.
- 14. Restore location as per BLM requirements.