

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Follow instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-P1424.
5. LEASE DESIGNATION AND SERIAL NO.

NML 00070
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Aztec Oil & Gas Company		8. FARM OR LEASE NAME Robinson	
3. ADDRESS OF OPERATOR Drawer 570, Farmington, New Mexico		9. WELL NO. #1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL & 990' FWL		10. FIELD AND POOL, OR WILDCAT West Kutz Pictured Cliffs	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section ²² 27-28N-13W	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6049'		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:


WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

PROPOSE TO:

1. Spot cement plug across perfs 1727 to 1772, top of plug at 1680'.
2. Perforate Ojo Alamo at 400' and squeeze with 50 sxs. Spot 100' plug inside pipe.
3. Squeeze bradenhead with 50 sxs.
4. Spot 10' plug at surface.
5. Install dry hole marker.
6. Clean location.



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE District Superintendent DATE 12-18-72

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: