

6--5-59

F. Loc. 790/S; 790/E Elev. 5947 DF 6-5-59 Spd. 6-5-59 Comp. 6-5-59 TD 6-5-59 PB 6-5-59

Casing S. 199 @ 100 W 100 Sx. Int. @ W Sx. Pr. 5 @ 100 W 100 Sx. T. 100 @ 100

Csg. Perf. 6-23-59 Prod. Stim. SUP - 2-10-59

I.P. 100 BO/D MCF/D After 100 Hrs. SICP 100 PSI After 100 Days GOR 100 Grav. 100 1st Del. 100

TOPS		NITD	Well Log	TEST					DATA		
Kirtland		C-102	Plot	Schd.	PC	Q	PW	PD	D	Ref. No.	
Fruitland		C-103	Electric Log	7/2/59	1633	1600		517			
Pictured Cliffs		C-104	C-110	10-2-59	1520	1500		600			
Cliff House											
Menefee		Ditr	Dfa								
Point Lookout		Datr	Dac								
Mancos		Remarks									
Gallup		Dakota zone abandoned 8-4-80 DC R-1740 E 320		6/6/59	1200	1200		500			
Dakota	6214			7/3/59	1100	1100		400			
Morrison				9/3/59	1144	1144		477	572	SS	
Entrada				Disconnect		10-27-75					#3989
Su. Co.											
Yuma											
Ph. dat.	-142										

DP Jan. Feb. Mar. Apr. May June July Aug. Sept. Oct. Nov. Dec. No. 1